

Cleanup Site Details

Cleanup Site ID: 5051

Cleanup Site ID: 5051 Facility/Site ID: 2030 UST ID: 97428 [Site Page](#) [Site Documents](#) [View Map](#)

Cleanup Site Name: Shell Oil Harbor Island Terminal

[Glossary](#)

Alternate Names: EQUILON, EQUILON ENTERPRISES, EQUILON ENTERPRISES LLC, EQUILON ENTERPRISES LUBRICANTS PLANT, EQUILON SEATTLE DISTRIBUTION TERMINAL, EQUILON SEATTLE DISTRIBUTION TERMINAL, Shell Oil Harbor Island Terminal, SHELL OIL PRODUCT SEATTLE TERMINAL, SHELL OIL PRODUCTS US 13TH AVE SW, TEXACO MARKETING & REFINING HARBOR ISLAND

LOCATION

Address: 2555 13TH AVE SW **City:** SEATTLE **Zip Code:** 98134 **County:** King
Latitude: 47.58243 **Longitude:** -122.35206 **WRIA:** 9 **Legislative District:** 34 **Congressional District:** 7 **TRS:** 24N 4E 7

DETAIL

Status: Construction Complete-Performance Monitoring **NFA Received?** No **Is PSI site?** Yes
Statute: MTCA **NFA Date:** N/A **Current VCP?** No **Past VCP?** No
Site Rank: N/A **NFA Reason:** N/A **Brownfield?** No
Site Manager: Atkins, Vance **Responsible Unit:** Northwest **Active Institutional Control?** No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Shell Oil Products Harbor Island Terminal	Upland	Construction Complete-Performance Monitoring	NW	Atkins, Vance	Ecology-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Benzene	C	C				
Halogenated Organics	S	S	S			
Lead	C	C				
Metals - Other	S	S	S			
Metals Priority Pollutants	S		S			
Pesticides-Unspecified	S	S	S			
Petroleum-Diesel	C	C	RB			
Petroleum-Gasoline	C	C	RB			
Petroleum-Other	C	C	RB			
Polychlorinated biPhenyls (PCB)	S	S	S			
Polycyclic Aromatic Hydrocarbons	C	C	RB			

Key:
B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

Cleanup Site Details

Cleanup Site ID: 5051

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
Site Discovery/Release Report Received	Completed		3/1/1988
Remedial Investigation and/or Feasibility Study	Completed	8/1/1988	7/1/1990
LUST - Notification	Completed		8/19/1992
National Priorities Listing	Completed		8/30/1992
Remedial Investigation and/or Feasibility Study	Completed	3/1/1993	4/30/1997
LUST - Report Received	Completed		3/21/1994
LUST - Report Received	Completed		3/21/1994
Cleanup Action Plan	Completed	12/12/1996	3/25/1999
Order/Decree/Amendment	In Process	10/5/1998	
Cleanup Action - Engineering Design	Completed	4/9/1999	2/28/2002
Cleanup - Construction	Completed	2/28/2002	6/1/2005
Periodic Review	Completed	5/1/2005	7/31/2005
Periodic Review	Completed		9/24/2010
Initial Investigation / Federal Preliminary Assessment	Completed		4/21/2011
Periodic Review	Completed		2/26/2015
Cleanup - Performance Monitoring	In Process	4/1/2016	
Periodic Review	Completed	3/11/2020	9/16/2020
LUST - Report Received	Completed		5/17/2021
Non-LUST Ind Report Received	Completed		8/31/2021
Non-LUST Ind Report Received	Completed		2/15/2022
Non-LUST Ind Report Received	Completed		8/15/2022
Non-LUST Ind Report Received	Completed		10/17/2022
SHARP Assessment	Completed		4/15/2024
Periodic Review	Planned	3/11/2025	1/1/1900