

Cleanup Site Details

Cleanup Site ID: 5055

Cleanup Site ID: 5055 Facility/Site ID: 2067 UST ID: 515 Site Page Site Documents View Map

Cleanup Site Name: Maralco Glossary

Alternate Names: HALPIN LYON COMPANY, HALPIN-LYON COMPANY, MARALCO, MARALCO Restoration Project

LOCATION

Address: 7730 S 202ND ST City: KENT Zip Code: 98032 County: King

Latitude: 47.42026 Longitude: -122.23567 WRIA: 9 Legislative District: 33 Congressional District: 9 TRS: 22N 4E 1

DETAIL

Status: Cleanup Started NFA Received? No Is PSI site? No

Statute: MTCA NFA Date: N/A Current VCP? No Past VCP? Yes

Site Rank: 2 - Moderate-High Risk NFA Reason: N/A Brownfield? No

Site Manager: Bianco, Paul Responsible Unit: Hazardous Waste Active Institutional Control? No

CLEANUP UNITS

 Cleanup Unit Name
 Unit Type
 Unit Status
 Resp Unit
 Unit Manager
 Current Process

 Maralco
 Upland
 Cleanup Started
 HWTR
 Bianco, Paul
 Ecology-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type Restriction Media Restrictions/Requirements Date Recording Number County Tax Parcel

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

	MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock	
Conventional Contaminants, Inorganic		С	S				
Metals - Other	С	С	S				
Petroleum-Diesel	С	С					

Key:

B - Below Cleanup Level
S - Suspected
C - Confirmed Above Cleanup Level
R - Remediated

RA - Remediated-Above RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Site Discovery/Release Report Received	Completed		1/1/1986
Order/Decree/Amendment	Completed	1/2/1986	1/1/1987
Placement of Lien	Completed	6/27/1988	12/20/2024
Interim Action	Completed	7/1/1988	3/30/1989
Remedial Investigation and/or Feasibility Study	Completed	4/15/1990	2/28/1991
Remedial Investigation and/or Feasibility Study	Completed	4/15/1990	3/1/1991
Site Hazard Assessment	Completed	6/25/1990	8/15/1990
Hazardous Sites Listing	Completed		8/15/1990

Toxics Cleanup Program Report Generated: 11/16/2025 Page 1 of 2



Cleanup Site Details

ECOLOGY Cleanup Site Details Cleanup Site ID: 5						
SITE ACTIVITIES						
Activity	Status	Start Date	End Date/ Completion Date			
Interim Action	Completed	10/1/1991	11/30/1991			
LUST - Report Received	Completed		5/16/2003			
LUST - Notification	Completed		2/9/2005			
LUST - Report Received	Completed		2/9/2005			
VCP Opinion on Remedial Investigation Work Plan	Completed	2/9/2005	4/21/2005			
LUST - Report Received	Completed		4/26/2005			
LUST - Report Received	Completed		6/13/2005			
LUST - Report Received	Completed		9/13/2005			
LUST - Report Received	Completed		11/17/2005			
VCP Status Request	Completed	7/23/2012	8/23/2012			
LUST - Report Received	Completed		3/18/2022			
VCP Opinion on Remedial Investigation Work Plan	Completed	3/18/2022	8/24/2022			
VCP Receipt of Plan or Report	Completed		7/6/2023			
VCP Receipt of Plan or Report	Completed		7/25/2023			
Order/Decree/Amendment	In Process	7/28/2023				
VCP Technical Assistance	Completed		7/31/2023			
Remedial Investigation and/or FS Work Plan	Completed	1/17/2024	1/27/2025			
Interim Action - Plan	Completed	3/22/2024	12/30/2024			
SHARP Assessment	Completed		7/24/2024			

In Process

In Process

10/1/2024

4/1/2025

Interim Action - Construction

Remedial Investigation and/or Feasibility Study