

Cleanup Site Details

Cleanup Site ID: 5056

Cleanup Site ID: 5056 Facility/Site ID: 2072 UST ID: 8218 [Site Page](#) [Site Documents](#) [View Map](#)

Cleanup Site Name: 8801 E Marginal Way S [Glossary](#)

Alternate Names: 8801 E MARGINAL WAY S, 8801 E MARIGINAL WAY S, 8801 Site, INSURANCE AUTO AUCTIONS TUKWILA, KENWORTH TRUCK CO TUK, PACCAR INC

LOCATION

Address: 8801 E MARGINAL WAY S City: TUKWILA Zip Code: 98108 County: King
Latitude: 47.52215 Longitude: -122.30153 WRIA: 9 Legislative District: 11 Congressional District: 9 TRS: 24N 4E 33

DETAIL

Status: Cleanup Started NFA Received? No Is PSI site? No
Statute: MTCA NFA Date: N/A Current VCP? No Past VCP? Yes
Site Rank: 1 - Highest Assessed Risk NFA Reason: N/A Brownfield? No
Site Manager: Johnson, Beau Responsible Unit: Northwest Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
8801 E Marginal Way S	Upland	Cleanup Started	NW	Johnson, Beau	Ecology-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
There are no current Institutional Controls in effect for this site.						

AFFECTED MEDIA & CONTAMINANTS

Contaminant	MEDIA					
	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Halogenated Organics	C	C	S		C	
Metals Priority Pollutants	C	C	S			
Non-Halogenated Solvents	C	C	S			
Petroleum-Diesel		C	C			
Petroleum-Gasoline	C	C			C	
Petroleum-Other	S	C	C			
Phenolic Compounds			S			
Polychlorinated biPhenyls (PCB)	C	C				
Polycyclic Aromatic Hydrocarbons	C	C				

Key:
B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/Completion Date
Order/Decree/Amendment	In Process		

Cleanup Site Details

Cleanup Site ID: 5056

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
Remedial Investigation and/or Feasibility Study	Completed	7/1/1988	9/30/1994
Remedial Investigation and/or Feasibility Study	Canceled	1/1/1994	11/14/2008
LUST - Notification	Completed		5/13/1997
LUST - Report Received	Completed		8/8/1999
LUST - Report Received	Completed		2/11/2000
VCP Opinion on Remedial Investigation Work Plan	Canceled	10/24/2000	1/1/1900
LUST - Report Received	Completed		6/6/2003
Site Characterization	Canceled	10/1/2006	6/30/2009
Order/Decree/Amendment	In Process	10/4/2006	
O & M	In Process	4/1/2007	
Site Hazard Assessment/Federal Site Inspection	Completed	1/16/2008	7/7/2008
Remedial Investigation and/or Feasibility Study	Completed	5/16/2008	3/18/2011
Hazardous Sites Listing/NPL	Completed		7/7/2008
Cleanup Action Plan	Canceled	1/5/2009	2/8/2010
Remedial Investigation and/or Feasibility Study	Completed	1/1/2012	7/27/2020
Interim Action - Plan	Completed	5/30/2013	7/27/2020
Interim Action - Construction	Completed	7/1/2021	10/10/2023
Cleanup Action Plan	In Process	1/1/2024	