

Cleanup Site Details

Cleanup Site ID: 5056

Cleanup Site ID: 5056 Facility/Site ID: 2072 UST ID: 8218 Site Page Site Documents View Map

Cleanup Site Name: 8801 E Marginal Way S

Alternate Names: 8801 E MARGINAL WAY S, 8801 E MARIGINAL WAY S, 8801 Site, INSURANCE AUTO AUCTIONS TUKWILA, KENWORTH

TRUCK CO TUK, PACCAR, PACCAR INC

LOCATION

Address: 8801 E MARGINAL WAY S City: TUKWILA Zip Code: 98108 County: King

Latitude: 47.52215 Longitude: -122.30153 WRIA: 9 Legislative District: 11 Congressional District: 9 TRS: 24N 4E 33

DETAIL

Status: Cleanup Started NFA Received? No Is PSI site? No

Statute: MTCA NFA Date: N/A Current VCP? No Past VCP? Yes

Site Rank: 1 - Highest Assessed Risk NFA Reason: N/A Brownfield? No

Site Manager: Johnson, Beau Responsible Unit: Northwest Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
8801 E Marginal Way S	Upland	Cleanup Started	NW	Johnson, Beau	Ecology-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restrictions/Requirements	strument Type Restriction Media	Date	Recording Number	Recording County	Tax Parcel
-----------------	---------------------------	---------------------------------	------	---------------------	---------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

MEDIA						
Soil	Groundwater	Surface Water	Sediment	Air	Bedrock	
С	С	S		С		
С	С	S				
С	С	S				
	С	С				
С	С			С		
S	С	С				
		S				
С	С					
С	С					
	C C C S	C C C C C C C C C C C C C C C C C C C	Soil Groundwater Surface Water C C S C C S C C C C C C S C C S C C C C C	Soil Groundwater Surface Water Sediment C C S C C S C C C C C C S C C C C S C C C	Soil Groundwater Surface Water Sediment Air C C S C C C S C C C C C C C C C S C C S C C C C	

Key:

B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Site Discovery/Release Report Received	Completed		3/1/1988

Toxics Cleanup Program Report Generated: 11/11/2025 Page 1 of 2



Cleanup Site Details

SITE ACTIVITIES					
Activity	Status	Start Date	End Date/ Completion Date		
Remedial Investigation and/or Feasibility Study	Completed	7/1/1988	9/30/1994		
Remedial Investigation and/or Feasibility Study	Canceled	1/1/1994	11/14/2008		
LUST - Notification	Completed		5/13/1997		
LUST - Report Received	Completed		8/8/1999		
LUST - Report Received	Completed		2/11/2000		
VCP Opinion on Remedial Investigation Work Plan	Canceled	10/24/2000	1/1/1900		
LUST - Report Received	Completed		6/6/2003		
Site Characterization	Canceled	10/1/2006	6/30/2009		
Order/Decree/Amendment	In Process	10/4/2006			
O & M	In Process	4/1/2007			
Site Hazard Assessment	Completed	1/16/2008	7/7/2008		
Remedial Investigation and/or Feasibility Study	Completed	5/16/2008	3/18/2011		
Hazardous Sites Listing	Completed		7/7/2008		
Order/Decree/Amendment	In Process	9/12/2008			
Cleanup Action Plan	Canceled	1/5/2009	2/8/2010		
Remedial Investigation and/or Feasibility Study	Completed	1/1/2012	7/27/2020		
Interim Action - Plan	Completed	5/30/2013	7/27/2020		
Interim Action - Construction	Completed	7/1/2021	10/10/2023		
Cleanup Action Plan	In Process	1/1/2024			

Cleanup Site ID: 5056