DEPARTMENT OF ECOLOGY State of Washington

Cleanup Site Details

Cleanup Site ID: 5056

Cleanup Site ID: 5056 **Facility/Site ID:** 2072 **UST ID:** 8218 Site Page | Site Documents | View Map

Cleanup Site Name: 8801 E Marginal Way S Glossary

Alternate Names: 8801 E MARGINAL WAY S, 8801 E MARIGINAL WAY S, 8801 Site, INSURANCE AUTO AUCTIONS TUKWILA, KENWORTH TRUCK CO TUK, PACCAR, PACCAR INC

LOCATION

Address: 8801 E MARGINAL WAY S **City:** TUKWILA **Zip Code:** 98108 **County:** King

Latitude: 47.52215 **Longitude:** -122.30153 **WRIA:** 9 **Legislative District:** 11 **Congressional District:** 9 **TRS:** 24N 4E 33

DETAIL

Status: Cleanup Started **NFA Received?** No **Is PSI site?** No

Statute: MTCA **NFA Date:** N/A **Current VCP?** No **Past VCP?** Yes

Site Rank: 1 - Highest Assessed Risk **NFA Reason:** N/A **Brownfield?** No

Site Manager: Johnson, Beau **Responsible Unit:** Northwest **Active Institutional Control?** No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
8801 E Marginal Way S	Upland	Cleanup Started	NW	Johnson, Beau	Ecology-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
There are no current Institutional Controls in effect for this site.						

AFFECTED MEDIA & CONTAMINANTS

	MEDIA					
Contaminant	**Soil**	**Groundwater**	**Surface Water**	**Sediment**	**Air**	**Bedrock**
Halogenated Organics	C	C	S		C	
Metals Priority Pollutants	C	C	S			
Non-Halogenated Solvents	C	C	S			
Petroleum-Diesel		C	C			
Petroleum-Gasoline	C	C			C	
Petroleum-Other	S	C	C			
Phenolic Compounds			S			
Polychlorinated biPhenyls (PCB)	C	C				
Polycyclic Aromatic Hydrocarbons	C	C				

Key:
B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Site Discovery/Release Report Received	Completed		3/1/1988

Cleanup Site Details

Cleanup Site ID: 5056

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Remedial Investigation and/or Feasibility Study	Completed	7/1/1988	9/30/1994
Remedial Investigation and/or Feasibility Study	Canceled	1/1/1994	11/14/2008
LUST - Notification	Completed		5/13/1997
LUST - Report Received	Completed		8/8/1999
LUST - Report Received	Completed		2/11/2000
VCP Opinion on Remedial Investigation Work Plan	Canceled	10/24/2000	1/1/1900
LUST - Report Received	Completed		6/6/2003
Site Characterization	Canceled	10/1/2006	6/30/2009
Order/Decree/Amendment	In Process	10/4/2006	
O & M	In Process	4/1/2007	
Site Hazard Assessment	Completed	1/16/2008	7/7/2008
Remedial Investigation and/or Feasibility Study	Completed	5/16/2008	3/18/2011
Hazardous Sites Listing	Completed		7/7/2008
Order/Decree/Amendment	In Process	9/12/2008	
Cleanup Action Plan	Canceled	1/5/2009	2/8/2010
Remedial Investigation and/or Feasibility Study	Completed	1/1/2012	7/27/2020
Interim Action - Plan	Completed	5/30/2013	7/27/2020
Interim Action - Construction	Completed	7/1/2021	10/10/2023
Cleanup Action Plan	In Process	1/1/2024	