

# Cleanup Site Details

Cleanup Site ID: 5056

Cleanup Site ID: 5056      Facility/Site ID: 2072      UST ID: 8218      [Site Page](#)      [Site Documents](#)      [View Map](#)

Cleanup Site Name: 8801 E Marginal Way S      [Glossary](#)

**Alternate Names:** 8801 E MARGINAL WAY S, 8801 E MARIGINAL WAY S, 8801 Site, INSURANCE AUTO AUCTIONS TUKWILA, KENWORTH TRUCK CO TUK, PACCAR, PACCAR INC

## LOCATION

**Address:** 8801 E MARGINAL WAY S      **City:** TUKWILA      **Zip Code:** 98108      **County:** King  
**Latitude:** 47.52215      **Longitude:** -122.30153      **WRIA:** 9      **Legislative District:** 11      **Congressional District:** 9      **TRS:** 24N 4E 33

## DETAIL

**Status:** Cleanup Started      **NFA Received?** No      **Is PSI site?** No  
**Statute:** MTCA      **NFA Date:** N/A      **Current VCP?** No      **Past VCP?** Yes  
**Site Rank:** 1 - Highest Assessed Risk      **NFA Reason:** N/A      **Brownfield?** No  
**Site Manager:** Johnson, Beau      **Responsible Unit:** Northwest      **Active Institutional Control?** No

## CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
8801 E Marginal Way S	Upland	Cleanup Started	NW	Johnson, Beau	Ecology-supervised or conducted

## ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

## AFFECTED MEDIA & CONTAMINANTS

MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Halogenated Organics	C	C	S		C	
Metals Priority Pollutants	C	C	S			
Non-Halogenated Solvents	C	C	S			
Petroleum-Diesel		C	C			
Petroleum-Gasoline	C	C			C	
Petroleum-Other	S	C	C			
Phenolic Compounds			S			
Polychlorinated biPhenyls (PCB)	C	C				
Polycyclic Aromatic Hydrocarbons	C	C				

**Key:**  
B - Below Cleanup Level      C - Confirmed Above Cleanup Level      RA - Remediated-Above  
S - Suspected      R - Remediated      RB - Remediated-Below

## SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Site Discovery/Release Report Received	Completed		3/1/1988

# Cleanup Site Details

Cleanup Site ID: 5056

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
Remedial Investigation and/or Feasibility Study	Completed	7/1/1988	9/30/1994
Remedial Investigation and/or Feasibility Study	Canceled	1/1/1994	11/14/2008
LUST - Notification	Completed		5/13/1997
LUST - Report Received	Completed		8/8/1999
LUST - Report Received	Completed		2/11/2000
VCP Opinion on Remedial Investigation Work Plan	Canceled	10/24/2000	1/1/1900
LUST - Report Received	Completed		6/6/2003
Site Characterization	Canceled	10/1/2006	6/30/2009
Order/Decree/Amendment	In Process	10/4/2006	
O & M	In Process	4/1/2007	
Site Hazard Assessment	Completed	1/16/2008	7/7/2008
Remedial Investigation and/or Feasibility Study	Completed	5/16/2008	3/18/2011
Hazardous Sites Listing	Completed		7/7/2008
Order/Decree/Amendment	In Process	9/12/2008	
Cleanup Action Plan	Canceled	1/5/2009	2/8/2010
Remedial Investigation and/or Feasibility Study	Completed	1/1/2012	7/27/2020
Interim Action - Plan	Completed	5/30/2013	7/27/2020
Interim Action - Construction	Completed	7/1/2021	10/10/2023
Cleanup Action Plan	In Process	1/1/2024	