

# Cleanup Site Details

Cleanup Site ID: 5056

Cleanup Site ID: 5056      Facility/Site ID: 2072      UST ID: 8218      [Site Page](#)      [Site Documents](#)      [View Map](#)

Cleanup Site Name: 8801 E Marginal Way S      [Glossary](#)

Alternate Names: 8801 E MARGINAL WAY S, 8801 E MARIGINAL WAY S, 8801 Site, INSURANCE AUTO AUCTIONS TUKWILA, KENWORTH TRUCK CO TUK, PACCAR INC

## LOCATION

Address: 8801 E MARGINAL WAY S      City: TUKWILA      Zip Code: 98108      County: King

Latitude: 47.52215      Longitude: -122.30153      WRIA: 9      Legislative District: 11      Congressional District: 9      TRS: 24N 4E 33

## DETAIL

Status: Cleanup Started      NFA Received? No      Is PSI site? No  
 Statute: MTCA      NFA Date: N/A      Current VCP? No      Past VCP? Yes  
 Site Rank: 1 - Highest Assessed Risk      NFA Reason: N/A      Brownfield? No  
 Site Manager: Johnson, Beau      Responsible Unit: Northwest      Active Institutional Control? No

## CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
8801 E Marginal Way S	Upland	Cleanup Started	NW	Johnson, Beau	Ecology-supervised or conducted

## ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

## AFFECTED MEDIA & CONTAMINANTS

Contaminant	MEDIA					
	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Halogenated Organics	C	C	S		C	
Metals Priority Pollutants	C	C	S			
Non-Halogenated Solvents	C	C	S			
Petroleum-Diesel		C	C			
Petroleum-Gasoline	C	C			C	
Petroleum-Other	S	C	C			
Phenolic Compounds			S			
Polychlorinated biPhenyls (PCB)	C	C				
Polycyclic Aromatic Hydrocarbons	C	C				

Key:  
 B - Below Cleanup Level      C - Confirmed Above Cleanup Level      RA - Remediated-Above  
 S - Suspected      R - Remediated      RB - Remediated-Below

## SITE ACTIVITIES

Activity	Status	Start Date	End Date/Completion Date
Order/Decree/Amendment	In Process		

# Cleanup Site Details

Cleanup Site ID: 5056

<b>SITE ACTIVITIES</b>			
<b>Activity</b>	<b>Status</b>	<b>Start Date</b>	<b>End Date/ Completion Date</b>
Remedial Investigation and/or Feasibility Study	Completed	7/1/1988	9/30/1994
Remedial Investigation and/or Feasibility Study	Canceled	1/1/1994	11/14/2008
LUST - Notification	Completed		5/13/1997
LUST - Report Received	Completed		8/8/1999
LUST - Report Received	Completed		2/11/2000
VCP Opinion on Remedial Investigation Work Plan	Canceled	10/24/2000	1/1/1900
LUST - Report Received	Completed		6/6/2003
Site Characterization	Canceled	10/1/2006	6/30/2009
Order/Decree/Amendment	In Process	10/4/2006	
O & M	In Process	4/1/2007	
Site Hazard Assessment/Federal Site Inspection	Completed	1/16/2008	7/7/2008
Remedial Investigation and/or Feasibility Study	Completed	5/16/2008	3/18/2011
Hazardous Sites Listing/NPL	Completed		7/7/2008
Cleanup Action Plan	Canceled	1/5/2009	2/8/2010
Remedial Investigation and/or Feasibility Study	Completed	1/1/2012	7/27/2020
Interim Action - Plan	Completed	5/30/2013	7/27/2020
Interim Action - Construction	Completed	7/1/2021	10/10/2023
Cleanup Action Plan	In Process	1/1/2024	