

Cleanup Site Details

Cleanup Site ID: 5059

Cleanup Site ID: 5059 Facility/Site ID: 2101 UST ID: 10408 [Site Page](#) [Site Documents](#) [View Map](#)

Cleanup Site Name: Boeing Developmental Center [Glossary](#)

Alternate Names: BOEING A & M DEVELOPMENTAL CENTER, BOEING BAS DEVELOPMNT CTR, BOEING DEVELOPMENTAL CENTER, DEVELOPMENTAL CENTER

LOCATION

Address: 9725 E MARGINAL WAY S City: TUKWILA Zip Code: 98108 County: King
Latitude: 47.51547 Longitude: -122.29746 WRIA: 9 Legislative District: 11 Congressional District: 9 TRS: 23N 4E 4

DETAIL

Status: Cleanup Started NFA Received? No Is PSI site? No
Statute: MTCA (RCRA Corrective Action) NFA Date: N/A Current VCP? No Past VCP? Yes
Site Rank: 1 - Highest Assessed Risk NFA Reason: N/A Brownfield? No
Site Manager: Myers, Michelle Responsible Unit: Hazardous Waste Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Boeing Developmental Center	Upland	Cleanup Started	HWTR	Myers, Michelle	Ecology-supervised or conducted
Boeing DC South Storm Drain System	Upland	Cleanup Started	HWTR	Myers, Michelle	Ecology-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Halogenated Organics	C	C	S		S	
Metals Priority Pollutants	S	C	S		S	
Non-Halogenated Solvents	C	C	S		S	
Petroleum Products-Unspecified			S		S	
Petroleum-Gasoline	C	C				
Polychlorinated biPhenyls (PCB)	B					
Polycyclic Aromatic Hydrocarbons	S	C				

Key:
B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Site Discovery/Release Report Received	Completed		3/1/1988
LUST - Notification	Completed		7/20/1989
LUST - Report Received	Completed		12/5/1990

Cleanup Site Details

Cleanup Site ID: 5059

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
LUST - Report Received	Completed		2/26/1993
LUST - Report Received	Completed		2/26/1993
VCP Opinion on Cleanup Action	Completed	9/22/1999	12/24/2009
VCP Opinion on Site Cleanup	Completed	3/25/2003	12/24/2009
Early Notice Letter(s)	Completed		3/20/2018
Site Hazard Assessment	Completed	12/13/2018	1/31/2019
Hazardous Sites Listing	Completed		2/13/2019
Order/Decree/Amendment	In Process	7/23/2019	