

# Cleanup Site Details

Cleanup Site ID: 5059

Cleanup Site ID: 5059      Facility/Site ID: 2101      UST ID: 10408      [Site Page](#)      [Site Documents](#)      [View Map](#)

Cleanup Site Name: Boeing Developmental Center      [Glossary](#)

**Alternate Names:** BOEING A & M DEVELOPMENTAL CENTER, BOEING BAS DEVELOPMNT CTR, Boeing DC South Storm Drain System, BOEING DEVELOPMENTAL CENTER, DEVELOPMENTAL CENTER

## LOCATION

**Address:** 9725 E MARGINAL WAY S      **City:** TUKWILA      **Zip Code:** 98108      **County:** King  
**Latitude:** 47.51547      **Longitude:** -122.29746      **WRIA:** 9      **Legislative District:** 11      **Congressional District:** 9      **TRS:** 23N 4E 4

## DETAIL

**Status:** Cleanup Started      **NFA Received?** No      **Is PSI site?** No  
**Statute:** MTCA (RCRA Corrective Action)      **NFA Date:** N/A      **Current VCP?** No      **Past VCP?** Yes  
**Site Rank:** 1 - Highest Assessed Risk      **NFA Reason:** N/A      **Brownfield?** No  
**Site Manager:** Myers, Michelle      **Responsible Unit:** Hazardous Waste      **Active Institutional Control?** No

## CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Boeing Developmental Center	Upland	Cleanup Started	HWTR	Myers, Michelle	Ecology-supervised or conducted
Boeing DC South Storm Drain System	Upland	Cleanup Started	HWTR	Myers, Michelle	Ecology-supervised or conducted

## ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

## AFFECTED MEDIA & CONTAMINANTS

Contaminant	MEDIA					
	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Halogenated Organics	C	C	S		S	
Metals Priority Pollutants	S	C	S		S	
Non-Halogenated Solvents	C	C	S		S	
Petroleum Products-Unspecified			S		S	
Petroleum-Gasoline	C	C				
Polychlorinated biPhenyls (PCB)	B					
Polycyclic Aromatic Hydrocarbons	S	C				

**Key:**  
B - Below Cleanup Level      C - Confirmed Above Cleanup Level      RA - Remediated-Above  
S - Suspected      R - Remediated      RB - Remediated-Below

## SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Site Discovery/Release Report Received	Completed		3/1/1988
LUST - Notification	Completed		7/20/1989
LUST - Report Received	Completed		12/5/1990

# Cleanup Site Details

Cleanup Site ID: 5059

<b>SITE ACTIVITIES</b>			
<b>Activity</b>	<b>Status</b>	<b>Start Date</b>	<b>End Date/ Completion Date</b>
LUST - Report Received	Completed		2/26/1993
LUST - Report Received	Completed		2/26/1993
VCP Opinion on Cleanup Action	Completed	9/22/1999	12/24/2009
VCP Opinion on Site Cleanup	Completed	3/25/2003	12/24/2009
Early Notice Letter(s)	Completed		3/20/2018
Site Hazard Assessment	Completed	12/13/2018	1/31/2019
Hazardous Sites Listing	Completed		2/13/2019
Order/Decree/Amendment	In Process	7/23/2019	