

Cleanup Site Details

Cleanup Site ID: 5089

Cleanup Site ID: 5089 Facility/Site ID: 2322 UST ID: 5754 [Site Page](#) [Site Documents](#) [View Map](#)

Cleanup Site Name: Circle K 1461 [Glossary](#)

Alternate Names: CIRCLE K 01461, CIRCLE K 1461, CIRCLE K Sta 1461

LOCATION

Address: 2350 24TH AVE E City: SEATTLE Zip Code: 98112 County: King
Latitude: 47.64008 Longitude: -122.30182 WRIA: 8 Legislative District: 43 Congressional District: 7 TRS: 25N 4E 21

DETAIL

Status: Cleanup Started NFA Received? No Is PSI site? No
Statute: MTCA NFA Date: N/A Current VCP? No Past VCP? No
Site Rank: 3 - Moderate Risk NFA Reason: N/A Brownfield? No
Site Manager: Myers, Dale R Responsible Unit: Northwest Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Circle K 1461	Upland	Cleanup Started	NW	Myers, Dale R	Ecology-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

MEDIA

Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Benzene	C	C				
Non-Halogenated Solvents	C	C				
Petroleum-Gasoline	C	C				

Key:
B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/Completion Date
Site Discovery/Release Report Received	Completed		8/7/1989
LUST - Notification	Completed		8/7/1989
Initial Investigation / Federal Preliminary Assessment	Completed		10/12/1989
LUST - Report Received	Completed		3/6/1990
LUST - Report Received	Completed		8/23/1990
LUST - Report Received	Completed		11/9/1990
Early Notice Letter(s)	Completed		3/20/1991
Cleanup Action Plan	Completed	4/15/1991	7/1/1992

Cleanup Site Details

Cleanup Site ID: 5089

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
Order/Decree/Amendment	In Process	2/19/1992	
LUST - Report Received	Completed		6/1/1992
Remedial Investigation and/or Feasibility Study	Completed	6/1/1992	7/1/1992
O & M	Canceled	7/1/1992	6/30/2002
Cleanup - Construction	Canceled	7/1/1992	12/30/1998
Cleanup Action - Engineering Design	Canceled	7/1/1992	12/30/1998
LUST - Report Received	Completed		1/12/1993
LUST - Report Received	Completed		4/25/1994
Site Hazard Assessment/Federal Site Inspection	Completed	6/1/1994	6/30/1994
Hazardous Sites Listing/NPL	Completed		6/30/1994
LUST - Report Received	Completed		7/7/1998
LUST - Report Received	Completed		1/11/2000
LUST - Report Received	Completed		4/27/2001
LUST - Report Received	Completed		11/26/2003
LUST - Report Received	Completed		6/17/2005
O & M	Canceled	10/2/2006	6/20/2007
Remedial Investigation and/or Feasibility Study	Completed		9/17/2018
Cleanup Action Plan	Completed		9/17/2018