

Cleanup Site Details

Cleanup Site ID: 5119

Cleanup Site ID: 5119 Facility/Site ID: 2487 UST ID: 3583 [Site Page](#) [Site Documents](#) [View Map](#)

Cleanup Site Name: CHS Auburn

[Glossary](#)

Alternate Names: AUBURN ABANDONED FIRE STN, Cenex Harvest States Auburn, CENEX HARVEST STATES AUBURN 2, CENEX HARVEST STATES COOPERATIVES, CENEX VALLEY SUPPLY, CENEX VALLEY SUPPLY COOP, CHS Auburn, CHS AUBURN 2, CHS Inc, CHS Inc., CHS Northwest, Firehouse Square

LOCATION

Address: 238 8TH ST SE **City:** AUBURN **Zip Code:** 98002 **County:** King
Latitude: 47.30036 **Longitude:** -122.22528 **WRIA:** 10 **Legislative District:** 30 **Congressional District:** 8 **TRS:** 21N 5E 19

DETAIL

Status: Cleanup Started	NFA Received? No	Is PSI site? No
Statute: MTCA	NFA Date: N/A	Current VCP? No Past VCP? No
Site Rank: 3 - Moderate Risk	NFA Reason: N/A	Brownfield? No
Site Manager: Atkins, Vance	Responsible Unit: Northwest	Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
CHS AUBURN	Upland	Cleanup Started	NW	Atkins, Vance	Ecology-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Non-Halogenated Solvents	C	C				
Petroleum-Other	C	C				

Key:
B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Order/Decree/Amendment	In Process		
Initial Investigation / Federal Preliminary Assessment	Completed		3/17/1994
LUST - Notification	Completed		5/17/1994
Site Discovery/Release Report Received	Completed		6/29/1994
Early Notice Letter(s)	Completed		7/22/1994
Emergency Action	Completed	10/1/1994	12/30/2012
Site Hazard Assessment	Completed	2/22/1995	6/29/1995
Hazardous Sites Listing	Completed		8/22/1995

Cleanup Site Details

Cleanup Site ID: 5119

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
Independent Report Review - Paid	Completed	10/25/1996	9/30/1998
Interim Action - Construction	Completed	4/15/1998	2/28/1999
LUST - Report Received	Completed		9/7/2001
LUST - Report Received	Completed		1/8/2003
Remedial Investigation and/or Feasibility Study	Completed	6/1/2006	8/6/2014
Cleanup Action Plan	Completed		6/20/2018
LUST - Report Received	Completed		2/10/2022
LUST - Report Received	Completed		8/1/2022
SHARP Assessment	Completed		4/12/2024