

Cleanup Site Details

Cleanup Site ID: 5119 Facility/Site ID: 2487 UST ID: 3583 Site Page Site Documents View Map

Cleanup Site ID: 5119

Cleanup Site Name: CHS Auburn Glossary

Alternate Names: AUBURN ABANDONED FIRE STN, Cenex Harvest States Auburn, CENEX HARVEST STATES AUBURN 2, CENEX HARVEST STATES COOPERATIVES, CENEX VALLEY SUPPLY, CENEX VALLEY SUPPLY COOP, CHS Auburn, CHS AUBURN 2, CHS Inc., CHS Inc., CHS

Northwest, Firehouse Square

LOCATION

Address: 238 8TH ST SE City: AUBURN Zip Code: 98002 County: King

Latitude: 47.30036 Longitude: -122.22528 WRIA: 10 Legislative District: 30 Congressional District: 8 TRS: 21N 5E 19

DETAIL

Status: Cleanup Started NFA Received? No Is PSI site? No

Statute: MTCA NFA Date: N/A Current VCP? No Past VCP? No

Site Rank: 3 - Moderate Risk NFA Reason: N/A Brownfield? No

Site Manager: Atkins, Vance Responsible Unit: Northwest Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
CHS AUBURN	Upland	Cleanup Started	NW	Atkins, Vance	Ecology-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction	Restrictions/Requirements	Date	Recording	Recording	Tay Parcel
Instrument Type	Media	Restrictions/Requirements	Date	Number	County	Tax Parcel

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

	MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock	
Non-Halogenated Solvents	С	С					
Petroleum-Other	С	С					

Key:

B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Order/Decree/Amendment	In Process		
Initial Investigation / Federal Preliminary Assessment	Completed		3/17/1994
LUST - Notification	Completed		5/17/1994
Site Discovery/Release Report Received	Completed		6/29/1994
Early Notice Letter(s)	Completed		7/22/1994
Emergency Action	Completed	10/1/1994	12/30/2012
Site Hazard Assessment	Completed	2/22/1995	6/29/1995
Hazardous Sites Listing	Completed		8/22/1995

Toxics Cleanup Program Report Generated: 11/9/2025 Page 1 of 2



SHARP Assessment

Cleanup Site Details

ECOLOGY State of Washington	Cleanup Site Details		Cleanup Site ID: 5119				
SITE ACTIVITIES							
Activity		Status	Start Date	End Date/ Completion Date			
Independent Report Review - Paid		Completed	10/25/1996	9/30/1998			
Interim Action - Construction		Completed	4/15/1998	2/28/1999			
LUST - Report Received		Completed		9/7/2001			
LUST - Report Received		Completed		1/8/2003			
Remedial Investigation and/or Feasibility Study		Completed	6/1/2006	8/6/2014			
Cleanup Action Plan		Completed		6/20/2018			
LUST - Report Received		Completed		2/10/2022			
LUST - Report Received		Completed		8/1/2022			

Completed

4/12/2024