

Cleanup Site Details

Cleanup Site ID: 5119

Cleanup Site ID: 5119 Facility/Site ID: 2487 UST ID: 3583 [Site Page](#) [Site Documents](#) [View Map](#)

Cleanup Site Name: CHS Auburn

[Glossary](#)

Alternate Names: AUBURN ABANDONED FIRE STN, Cenex Harvest States Auburn, CENEX HARVEST STATES AUBURN 2, CENEX HARVEST STATES COOPERATIVES, CENEX VALLEY SUPPLY, CENEX VALLEY SUPPLY COOP, CHS Auburn, CHS AUBURN 2, CHS Inc, CHS Inc., CHS Northwest, Firehouse Square

LOCATION

Address: 238 8TH ST SE **City:** AUBURN **Zip Code:** 98002 **County:** King
Latitude: 47.30036 **Longitude:** -122.22528 **WRIA:** 10 **Legislative District:** 30 **Congressional District:** 8 **TRS:** 21N 5E 19

DETAIL

| | | |
|-------------------------------------|------------------------------------|--|
| Status: Cleanup Started | NFA Received? No | Is PSI site? No |
| Statute: MTCA | NFA Date: N/A | Current VCP? No Past VCP? No |
| Site Rank: 3 - Moderate Risk | NFA Reason: N/A | Brownfield? No |
| Site Manager: Atkins, Vance | Responsible Unit: Northwest | Active Institutional Control? No |

CLEANUP UNITS

| Cleanup Unit Name | Unit Type | Unit Status | Resp Unit | Unit Manager | Current Process |
|-------------------|-----------|-----------------|-----------|---------------|---------------------------------|
| CHS AUBURN | Upland | Cleanup Started | NW | Atkins, Vance | Ecology-supervised or conducted |

ACTIVE INSTITUTIONAL CONTROLS

| Instrument Type | Restriction Media | Restrictions/Requirements | Date | Recording Number | Recording County | Tax Parcel |
|-----------------|-------------------|---------------------------|------|------------------|------------------|------------|
|-----------------|-------------------|---------------------------|------|------------------|------------------|------------|

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

| MEDIA | | | | | | |
|--------------------------|------|-------------|---------------|----------|-----|---------|
| Contaminant | Soil | Groundwater | Surface Water | Sediment | Air | Bedrock |
| Non-Halogenated Solvents | C | C | | | | |
| Petroleum-Other | C | C | | | | |

Key:
B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

| Activity | Status | Start Date | End Date/ Completion Date |
|--|------------|------------|---------------------------|
| Order/Decree/Amendment | In Process | | |
| Initial Investigation / Federal Preliminary Assessment | Completed | | 3/17/1994 |
| LUST - Notification | Completed | | 5/17/1994 |
| Site Discovery/Release Report Received | Completed | | 6/29/1994 |
| Early Notice Letter(s) | Completed | | 7/22/1994 |
| Emergency Action | Completed | 10/1/1994 | 12/30/2012 |
| Site Hazard Assessment/Federal Site Inspection | Completed | 2/22/1995 | 6/29/1995 |
| Hazardous Sites Listing/NPL | Completed | | 8/22/1995 |

Cleanup Site Details

Cleanup Site ID: 5119

| SITE ACTIVITIES | | | |
|---|-----------|------------|------------------------------|
| Activity | Status | Start Date | End Date/ Completion Date |
| Independent Report Review - Paid | Completed | 10/25/1996 | 9/30/1998 |
| Interim Action - Construction | Completed | 4/15/1998 | 2/28/1999 |
| LUST - Report Received | Completed | | 9/7/2001 |
| LUST - Report Received | Completed | | 1/8/2003 |
| Remedial Investigation and/or Feasibility Study | Completed | 6/1/2006 | 8/6/2014 |
| Cleanup Action Plan | Completed | | 6/20/2018 |
| LUST - Report Received | Completed | | 2/10/2022 |
| LUST - Report Received | Completed | | 8/1/2022 |