

Cleanup Site Details

Cleanup Site ID: 5127

Cleanup Site ID: 5127 Facility/Site ID: 2507 UST ID: 200090 Site Page Site Documents View Map

Cleanup Site Name: Bellevue Chrysler Plymouth

Alternate Names: BELLEVUE CHRYSLER PLYMOUTH, EASTSIDE CHRYSLER JEEP, EASTSIDE JEEP EAGLE

LOCATION

Address: 126 116TH AVE NE City: BELLEVUE Zip Code: 98004 County: King

Latitude: 47.61242 Longitude: -122.18431 WRIA: 8 Legislative District: 41 Congressional District: 9 TRS: 25N 5E 33

DETAIL

Status: No Further Action NFA Received? Yes Is PSI site? No

Statute: MTCA NFA Date: 5/17/2021 Current VCP? No Past VCP? Yes

Site Rank: N/A NFA Reason: Voluntary Cleanup Program Review Brownfield? No

Site Manager: Maurer, Christopher Responsible Unit: Northwest Active Institutional Control? No

CLEANUP UNITS

 Cleanup Unit Name
 Unit Type
 Unit Status
 Resp Unit
 Unit Manager
 Current Process

 Bellevue Chrysler Plymouth
 Upland
 No Further Action Required
 NW
 Maurer, Christopher
 Standard Voluntary Cleanup

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type Restriction Media Restrictions/Requirements Date Recording Number County Tax Parcel

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

	MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock	
Halogenated Organics	RB	RB					
Non-Halogenated Solvents	RB	RB					
Petroleum-Other	RB	RB					

Key:

B - Below Cleanup Level
S - Suspected
C - Confirmed Above Cleanup Level
R - Remediated

RA - Remediated-Above RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
LUST - Report Received	Completed		6/1/1988
LUST - Report Received	Completed		1/1/1989
LUST - Report Received	Completed		2/15/1989
LUST - Report Received	Completed		3/6/1989
LUST - Report Received	Completed		4/3/1989
LUST - Notification	Completed		4/6/1989
LUST - Report Received	Completed		5/4/1990
Site Discovery/Release Report Received	Completed		8/20/1993

Toxics Cleanup Program Report Generated: 10/22/2025 Page 1 of 2



Site Status Changed to NFA

Cleanup Site Details

ECOLOGY Cleanup	Cleanup Site Details		Cleanup Site ID: 5127				
SITE ACTIVITIES							
Activity	Status	Start Date	End Date/ Completion Date				
Initial Investigation / Federal Preliminary Assessment	Completed		11/3/1993				
Early Notice Letter(s)	Completed		10/18/1994				
VCP Opinion on Cleanup Action Plan	Completed	7/27/1998	1/26/2000				
Independent Report Review - Unpaid	Completed	7/28/1998	1/26/2000				
Site Status Changed to NFA	Completed		1/26/2000				
LUST - Report Received	Completed		6/19/2018				
Reopen Site	Completed		4/5/2019				
VCP Opinion on Site Cleanup	Completed	4/5/2019	5/17/2021				
LUST - Report Received	Completed		4/17/2019				
VCP Receipt of Plan or Report	Completed		6/17/2019				
VCP Receipt of Plan or Report	Completed		6/17/2019				
VCP Receipt of Plan or Report	Completed		2/6/2020				
VCP Receipt of Plan or Report	Completed		10/7/2020				

Completed

5/17/2021