

# Cleanup Site Details

Cleanup Site ID: 5127

Cleanup Site ID: 5127      Facility/Site ID: 2507      UST ID: 200090      [Site Page](#)      [Site Documents](#)      [View Map](#)

Cleanup Site Name: Bellevue Chrysler Plymouth      [Glossary](#)

Alternate Names: BELLEVUE CHRYSLER PLYMOUTH, EASTSIDE CHRYSLER JEEP, EASTSIDE JEEP EAGLE

## LOCATION

Address: 126 116TH AVE NE      City: BELLEVUE      Zip Code: 98004      County: King  
Latitude: 47.61242      Longitude: -122.18431      WRIA: 8      Legislative District: 41      Congressional District: 9      TRS: 25N 5E 33

## DETAIL

Status: No Further Action      NFA Received? Yes      Is PSI site? No  
Statute: MTCA      NFA Date: 5/17/2021      Current VCP? No      Past VCP? Yes  
Site Rank: N/A      NFA Reason: Voluntary Cleanup Program Review      Brownfield? No  
Site Manager: Maurer, Christopher      Responsible Unit: Northwest      Active Institutional Control? No

## CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Bellevue Chrysler Plymouth	Upland	No Further Action Required	NW	Maurer, Christopher	Standard Voluntary Cleanup

## ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

## AFFECTED MEDIA & CONTAMINANTS

### MEDIA

Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Halogenated Organics	RB	RB				
Non-Halogenated Solvents	RB	RB				
Petroleum-Other	RB	RB				

**Key:**  
B - Below Cleanup Level      C - Confirmed Above Cleanup Level      RA - Remediated-Above  
S - Suspected      R - Remediated      RB - Remediated-Below

## SITE ACTIVITIES

Activity	Status	Start Date	End Date/Completion Date
LUST - Report Received	Completed		6/1/1988
LUST - Report Received	Completed		1/1/1989
LUST - Report Received	Completed		2/15/1989
LUST - Report Received	Completed		3/6/1989
LUST - Report Received	Completed		4/3/1989
LUST - Notification	Completed		4/6/1989
LUST - Report Received	Completed		5/4/1990
Site Discovery/Release Report Received	Completed		8/20/1993

# Cleanup Site Details

Cleanup Site ID: 5127

<b>SITE ACTIVITIES</b>			
<b>Activity</b>	<b>Status</b>	<b>Start Date</b>	<b>End Date/ Completion Date</b>
Initial Investigation / Federal Preliminary Assessment	Completed		11/3/1993
Early Notice Letter(s)	Completed		10/18/1994
VCP Opinion on Cleanup Action Plan	Completed	7/27/1998	1/26/2000
Independent Report Review - Unpaid	Completed	7/28/1998	1/26/2000
Site Status Changed to NFA	Completed		1/26/2000
LUST - Report Received	Completed		6/19/2018
Reopen Site	Completed		4/5/2019
VCP Opinion on Site Cleanup	Completed	4/5/2019	5/17/2021
LUST - Report Received	Completed		4/17/2019
VCP Receipt of Plan or Report	Completed		6/17/2019
VCP Receipt of Plan or Report	Completed		6/17/2019
VCP Receipt of Plan or Report	Completed		2/6/2020
VCP Receipt of Plan or Report	Completed		10/7/2020
Site Status Changed to NFA	Completed		5/17/2021