

Cleanup Site Details

Cleanup Site ID: 5127

Cleanup Site ID: 5127 Facility/Site ID: 2507 UST ID: 200090 [Site Page](#) [Site Documents](#) [View Map](#)

Cleanup Site Name: Bellevue Chrysler Plymouth [Glossary](#)

Alternate Names: BELLEVUE CHRYSLER PLYMOUTH, EASTSIDE CHRYSLER JEEP, EASTSIDE JEEP EAGLE

LOCATION

Address: 126 116TH AVE NE City: BELLEVUE Zip Code: 98004 County: King
Latitude: 47.61242 Longitude: -122.18431 WRIA: 8 Legislative District: 41 Congressional District: 9 TRS: 25N 5E 33

DETAIL

Status: No Further Action NFA Received? Yes Is PSI site? No
Statute: MTCA NFA Date: 5/17/2021 Current VCP? No Past VCP? Yes
Site Rank: N/A NFA Reason: Voluntary Cleanup Program Review Brownfield? No
Site Manager: Maurer, Christopher Responsible Unit: Northwest Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Bellevue Chrysler Plymouth	Upland	No Further Action Required	NW	Maurer, Christopher	Standard Voluntary Cleanup

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

MEDIA

Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Halogenated Organics	RB	RB				
Non-Halogenated Solvents	RB	RB				
Petroleum-Other	RB	RB				

Key:
B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/Completion Date
LUST - Report Received	Completed		6/1/1988
LUST - Report Received	Completed		1/1/1989
LUST - Report Received	Completed		2/15/1989
LUST - Report Received	Completed		3/6/1989
LUST - Report Received	Completed		4/3/1989
LUST - Notification	Completed		4/6/1989
LUST - Report Received	Completed		5/4/1990
Site Discovery/Release Report Received	Completed		8/20/1993

Cleanup Site Details

Cleanup Site ID: 5127

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
Initial Investigation / Federal Preliminary Assessment	Completed		11/3/1993
Early Notice Letter(s)	Completed		10/18/1994
VCP Opinion on Cleanup Action Plan	Completed	7/27/1998	1/26/2000
Independent Report Review - Unpaid	Completed	7/28/1998	1/26/2000
Site Status Changed to NFA	Completed		1/26/2000
LUST - Report Received	Completed		6/19/2018
Reopen Site	Completed		4/5/2019
VCP Opinion on Site Cleanup	Completed	4/5/2019	5/17/2021
LUST - Report Received	Completed		4/17/2019
VCP Receipt of Plan or Report	Completed		6/17/2019
VCP Receipt of Plan or Report	Completed		6/17/2019
VCP Receipt of Plan or Report	Completed		2/6/2020
VCP Receipt of Plan or Report	Completed		10/7/2020
Site Status Changed to NFA	Completed		5/17/2021