

Cleanup Site Details

Cleanup Site ID: 5142

Cleanup Site ID: 5142 Facility/Site ID: 2544 UST ID: 6870 Site Page Site Documents View Map

Cleanup Site Name: Lakeside Industries Eastgate Glossary

Alternate Names: Eastgate Housing Campus, Lakeside Ind UST 6870, LAKESIDE INDUSTRIES BELLEVUE, LAKESIDE INDUSTRIES

EASTGATE, Polaris at Eastgate, Washington Asphalt Co

LOCATION

Address: 13620 SE EASTGATE WAY City: BELLEVUE Zip Code: 98005 County: King

Latitude: 47.58114 Longitude: -122.16007 WRIA: 8 Legislative District: 41 Congressional District: 9 TRS: 24N 5E 10

DETAIL

Status: Cleanup Started NFA Received? No Is PSI site? No

Statute: MTCA NFA Date: N/A Current VCP? No Past VCP? No

Site Rank: N/A NFA Reason: N/A Brownfield? No

Site Manager: Northwest Region Responsible Unit: Northwest Active Institutional Control? Yes

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process	
Lakeside Industries Eastgate LUST (Property)	Upland	No Further Action Required	PLIA	PLIA	PLIA Petroleum Technical Assistance Program	
Lakeside Industries Eastgate	Sediment	Awaiting Cleanup	NW	Northwest Region	Independent Action	
Lakeside Industries Eastgate Off- Property	Upland	Cleanup Started	NW	Northwest Region	Independent Action	

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
Environmental Covenant	Soil	Ongoing Maintenance of Remedy, Control Vapor/Gas, Other	11/13/2024	20241113000929	King	6838640000

Institutional Control documents may be available under the 'Site Documents' link at the top of the page. For more details on Institutional Controls, please see the **Environmental Covenants Registry List**.

AFFECTED MEDIA & CONTAMINANTS

	MEDIA							
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock		
Arsenic	С	С						
Halogenated Organics	RA	RA						
Lead	С	С	С	S				
Metals - Other	С	С	С					
Metals Priority Pollutants		RA						
Non-Halogenated Solvents	RA	С		S				
Other Halogenated Organics	С	С		S				
Other Non-Halogenated Organics	С	С						
Petroleum Products-Unspecified		RA						
Petroleum-Diesel	С	С		S				
Petroleum-Gasoline	С	С		S				
Petroleum-Other	С	С	С	S				

Toxics Cleanup Program Report Generated: 7/7/2025 Page 1 of 2



Polycyclic Aromatic Hydrocarbons

Contaminant

Cleanup Site Details

С

Cleanup Site ID: 5142 Soil Groundwater **Surface Water** Sediment Air Bedrock

Key:B - Below Cleanup Level
S - Suspected RA - Remediated-Above RB - Remediated-Below C - Confirmed Above Cleanup Level R - Remediated

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date			
LUST - Notification	Completed		9/30/1993			
Site Discovery/Release Report Received	Completed		11/9/1993			
Initial Investigation / Federal Preliminary Assessment	Completed		7/26/1995			
Early Notice Letter(s)	Completed		8/11/1995			
Initial Investigation / Federal Preliminary Assessment	Completed		3/8/2011			
Periodic Review	Planned	11/13/2029	1/1/1900			

Toxics Cleanup Program Report Generated: 7/7/2025 Page 2 of 2