

Cleanup Site Details

Cleanup Site ID: 5174

Cleanup Site ID: 5174 Facility/Site ID: 2670 UST ID: 4931 Site Page Site Documents View Map

Cleanup Site Name: Anacortes Port of Dakota Creek

Alternate Names: Anacortes Port of Dakota Creek, Dakota Creek Industries, DAKOTA CREEK INDUSTRIES INC, PORT OF ANACORTES

DAKOTA CREEK

LOCATION

Address: 115 Q Ave City: Anacortes Zip Code: 98221 County: Skagit

Latitude: 48.51975 Longitude: -122.60786 WRIA: 3 Legislative District: 40 Congressional District: 2 TRS: 35N 2E 18

DETAIL

Status: Cleanup Started NFA Received? No Is PSI site? Yes

Statute: MTCA NFA Date: N/A Current VCP? No Past VCP? Yes

Site Rank: 1 - Highest Assessed Risk NFA Reason: N/A Brownfield? No

Site Manager: Horne, David Responsible Unit: Headquarters Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Dakota Creek Shipyard Port of Anacortes	Upland	Construction Complete- Performance Monitoring	HQ	Horne, David	Ecology-supervised or conducted
Dakota Creek Industries Inc	Sediment	Cleanup Complete-Active O&M/Monitoring ongoing	HQ	Adolphson, Pete	Ecology-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	----------------------	---------------------------	------	---------------------	---------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

	MEDIA							
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock		
Benzene	В	В						
Dioxins/Furans	В	В						
Halogenated Organics			S	RB				
Halogenated Pesticides		В						
Metals - Other			S					
Metals Priority Pollutants	RA	С	S	RB				
Methyl tertiary-butyl ether	В	В						
Non-Halogenated Pesticides		В						
Non-Halogenated Solvents		В	S					
Other Non-Halogenated Organics		В						
Petroleum Products-Unspecified			S	RB				
Petroleum-Diesel	RB	В						
Petroleum-Gasoline	RB	В						

Toxics Cleanup Program Report Generated: 11/14/2024 Page 1 of 2



Cleanup Site Details

Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Petroleum-Other	RB	В				
Phenolic Compounds		В	S	RB		
Polychlorinated biPhenyls (PCB)	В			RB		
Polycyclic Aromatic Hydrocarbons	RA	С				

Key:B - Below Cleanup Level
S - Suspected

C - Confirmed Above Cleanup Level R - Remediated

RA - Remediated-Above RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Early Notice Letter(s)	Completed		4/11/1991
LUST - Notification	Completed		9/23/1991
VCP Opinion on Cleanup Action	Completed	3/28/2002	1/1/1900
VCP Opinion on Cleanup Action	Completed	1/2/2003	1/1/1900
Order/Decree/Amendment	Completed	11/12/2007	12/12/2007
Remedial Investigation and/or Feasibility Study	Completed	1/1/2008	10/27/2022
Interim Action - Plan	Completed	1/2/2008	4/1/2008
Site Hazard Assessment/Federal Site Inspection	Completed	1/11/2008	7/21/2008
Interim Action - Construction	Completed	6/1/2008	10/6/2010
Hazardous Sites Listing/NPL	Completed		7/21/2008
Cleanup Action Plan	Completed	3/1/2022	7/1/2022
Cleanup Action - Engineering Design	Completed	3/1/2022	11/1/2022
Order/Decree/Amendment	In Process	10/21/2022	
Cleanup - Construction	Completed	6/29/2023	8/8/2023
Cleanup - Performance Monitoring	In Process	11/22/2023	