

Cleanup Site Details

Cleanup Site ID: 5174

Cleanup Site ID: 5174 **Facility/Site ID:** 2670 **UST ID:** 4931 [Site Page](#) [Site Documents](#) [View Map](#)
Cleanup Site Name: Anacortes Port of Dakota Creek [Glossary](#)
Alternate Names: Anacortes Port of Dakota Creek, Dakota Creek Industries, DAKOTA CREEK INDUSTRIES INC, PORT OF ANACORTES DAKOTA CREEK

LOCATION

Address: 115 Q Ave **City:** Anacortes **Zip Code:** 98221 **County:** Skagit
Latitude: 48.51975 **Longitude:** -122.60786 **WRIA:** 3 **Legislative District:** 40 **Congressional District:** 2 **TRS:** 35N 2E 18

DETAIL

Status: Cleanup Started **NFA Received?** No **Is PSI site?** Yes
Statute: MTCA **NFA Date:** N/A **Current VCP?** No **Past VCP?** Yes
Site Rank: 1 - Highest Assessed Risk **NFA Reason:** N/A **Brownfield?** No
Site Manager: Horne, David **Responsible Unit:** Headquarters **Active Institutional Control?** No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Dakota Creek Shipyard Port of Anacortes	Upland	Construction Complete-Performance Monitoring	HQ	Horne, David	Ecology-supervised or conducted
Dakota Creek Industries Inc	Sediment	Cleanup Complete-Active O&M/Monitoring ongoing	HQ	Adolphson, Pete	Ecology-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

Contaminant	MEDIA					
	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Benzene	B	B				
Dioxins/Furans	B	B				
Halogenated Organics			S	RB		
Halogenated Pesticides		B				
Metals - Other			S			
Metals Priority Pollutants	RA	C	S	RB		
Methyl tertiary-butyl ether	B	B				
Non-Halogenated Pesticides		B				
Non-Halogenated Solvents		B	S			
Other Non-Halogenated Organics		B				
Petroleum Products-Unspecified			S	RB		
Petroleum-Diesel	RB	B				
Petroleum-Gasoline	RB	B				

Cleanup Site Details

Cleanup Site ID: 5174

Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Petroleum-Other	RB	B				
Phenolic Compounds		B	S	RB		
Polychlorinated biPhenyls (PCB)	B			RB		
Polycyclic Aromatic Hydrocarbons	RA	C				

Key:

B - Below Cleanup Level
S - Suspected

C - Confirmed Above Cleanup Level
R - Remediated

RA - Remediated-Above
RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Early Notice Letter(s)	Completed		4/11/1991
LUST - Notification	Completed		9/23/1991
VCP Opinion on Cleanup Action	Completed	3/28/2002	1/1/1900
VCP Opinion on Cleanup Action	Completed	1/2/2003	1/1/1900
Order/Decree/Amendment	Completed	11/12/2007	12/12/2007
Remedial Investigation and/or Feasibility Study	Completed	1/1/2008	10/27/2022
Interim Action - Plan	Completed	1/2/2008	4/1/2008
Site Hazard Assessment/Federal Site Inspection	Completed	1/11/2008	7/21/2008
Interim Action - Construction	Completed	6/1/2008	10/6/2010
Hazardous Sites Listing/NPL	Completed		7/21/2008
Cleanup Action Plan	Completed	3/1/2022	7/1/2022
Cleanup Action - Engineering Design	Completed	3/1/2022	11/1/2022
Order/Decree/Amendment	In Process	10/21/2022	
Cleanup - Construction	Completed	6/29/2023	8/8/2023
Cleanup - Performance Monitoring	In Process	11/22/2023	