DEPARTMENT ECOLOG State of Washingt	Y		Cleanu	p Site l	Deta	ails		Cl	eanup S	Site ID: 5174
Cleanup Site ID: 5174 Facility/Site ID: 2670				UST ID: 493	31	Site Page		Site Documents		<u>View Map</u>
Cleanup Site Name	: Anacortes Port of	of Dakota Cre	ek							<u>Glossary</u>
Alternate Names: A	Anacortes Port of D	akota Creek	, Dakota Creek	Industries, DAK	OTA CF	REEK INDUSTRI	ES INC	, PORT C	of anaco	ORTES
LOCATION										
Address: 115 Q Av	/e			City: Anacor	tes	Zip Code: 9	98221	Cou	nty: Skag	jit
Latitude: 48.51975	Longitude: -1	22.60786	WRIA: 3	Legislative D	istrict:	40 Congres	sional	District:	2 TR	3: 35N 2E 18
DETAIL										
Status: Construct Performance Monitor	ction Complete-	NFA	Received?	No		ls	s PSI si	te?	Yes	
Statute: MTCA	5	NFA	Date:	N/A		c	Current	VCP?	No Pa	st VCP? Yes
Site Rank: 1 - Highe	est Assessed Risk	NFA	Reason:	N/A		E	Brownfi	eld?	No	
Site Manager: Horn	ne, David	Resp	onsible Unit:	Headquarters		4	Active I	nstitutior	nal Contro	No No
CLEANUP UNITS										
Cleanup U	Cleanup Unit Name Unit Type		Unit \$	Unit Status		Unit Manager		Current Pro		rocess
Dakota Creek Shipya Anacortes	ard Port of	Upland		n Complete- e Monitoring	НQ	Horne, David		Ecology-supervised or conc		ed or conducted
				Cleanup Complete-Active O&M/Monitoring ongoing		Adolphson, Pete		Ecology-supervised or conducted		
ACTIVE INSTITUTIO	ONAL CONTROLS					•				
Instrument Type Restriction Media Restriction				rements	Date Recordin Number					Tax Parcel
There are no current										
AFFECTED MEDIA	& CONTAMINANT	S								
						ME	DIA			
Contaminant			Soi		lwater	Surface Water	Sec	diment	Air	Bedrock
Benzene			В	В						
Dioxins/Furans			В	В						
Halogenated Organics						S		RB		
Halogenated Pesticio	des			В						
Metals - Other						S				
Metals Priority Pollutants			RA			S	_	RB		
Methyl tertiary-butyl ether			В	B						
Non-Halogenated Pesticides				B						
Non-Halogenated Solvents Other Non-Halogenated Organics				B		S	_			
Petroleum Products-	-			B		S		RB		
Petroleum-Diesel				B B			_			
Petroleum-Gasoline			RE							
Toxics Cleanu	p Program		Repo	ort Generate	d: 7/13	3/2025			Pag	je 1 of 2



Cleanup Site Details

Cleanup Site ID: 5174

Contaminant		Soil	Groundwater	Surface Water	Sediment	Air	Bedrock	
Petroleum-Other		RB	В					
Phenolic Compounds			В	S	RB			
Polychlorinated biPhenyls (PCE	В			RB				
Polycyclic Aromatic Hydrocarbons		RA	С					
Key: B - Below Cleanup Level S - Suspected	C - Confirmed Above Clea R - Remediated	anup Level	RA - Remediate RB - Remediate					
SITE ACTIVITIES								
Activity		Status	Start Date		End Date/ Completion Date			
Early Notice Letter(s)				Completed		4/11/1991		
LUST - Notification				Completed			9/23/1991	
VCP Opinion on Cleanup Action				Completed	3/28/2002		1/1/1900	
VCP Opinion on Cleanup Action				Completed	1/2/2003	1/1/1900		
Order/Decree/Amendment				Completed	11/12/2007	/2007 12/28/2023		
Remedial Investigation and/or Feasibility Study				Completed	1/1/2008 10/2		0/27/2022	
Interim Action - Plan				Completed 1/2/2008		4/1/2008		
Site Hazard Assessment				Completed 1/11/2008		7/21/2008		
Interim Action - Construction				Completed 6/1/2008		10/6/2010		
Hazardous Sites Listing				Completed			7/21/2008	
Cleanup Action Plan				Completed 3/1/2022		7/1/2022		
Cleanup Action - Engineering Design				Completed	3/1/2022 11/1/20		11/1/2022	
Order/Decree/Amendment				In Process	10/21/2022			
Cleanup - Construction		Completed	6/29/2023 8/8		8/8/2023			
Cleanup - Performance Monito		Completed 11/22/2023			11/1/2024			
SHARP Assessment		Completed 7/17/2			7/17/2024			