

Cleanup Site ID: 5187

Cleanup Site Details

Facility/Site ID: 2783 UST ID: 6412 Site Page Site Documents View Map

Cleanup Site ID: 5187

Cleanup Site Name: Iron Mountain Quarry Granite Falls

Glossary

Alternate Names: Granco, GRANITE FALLS ROCK INC, IRON MOUNTAIN QUARRY GRANITE FALLS, MERIDIAN AGGREGAT, MERIDIAN

AGGREGATES GRANITE FALLS

LOCATION

Address: 21100 WAYSIDE MINE RD City: GRANITE FALLS Zip Code: 98252 County: Snohomish

Latitude: 48.09581 Longitude: -121.93486 WRIA: 5 Legislative District: 39 Congressional District: 1 TRS: 30N 7E 8

DETAIL

Status: No Further Action NFA Received? Yes Is PSI site? No

Statute: MTCA NFA Date: 12/28/1995 Current VCP? No Past VCP? No

Site Rank: N/A NFA Reason: Site Hazard Assessment Brownfield? No

Site Manager: Atkinson, Elaine Responsible Unit: Northwest Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Meridian Aggregates	Upland	No Further Action Required	NW	Atkinson, Elaine	No Process

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	----------------------	---------------------------	------	---------------------	---------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

	MEDIA					
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Metals Priority Pollutants	S	S	S		S	
Petroleum Products-Unspecified		S	S		S	
Petroleum-Other	С					

Key:

B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date	
LUST - Notification	Completed		6/20/1991	
Site Hazard Assessment	Completed	9/8/1995	12/28/1995	
Site Status Changed to NFA	Completed		12/28/1995	

Toxics Cleanup Program Report Generated: 10/22/2025 Page 1 of 1