

# Cleanup Site Details

Cleanup Site ID: 5208

Cleanup Site ID: 5208      Facility/Site ID: 3892      UST ID: 4099      [Site Page](#)    [Site Documents](#)    [View Map](#)  
 Cleanup Site Name: Kens Auto Wash II      [Glossary](#)  
 Alternate Names: KENS AUTO WASH II

## LOCATION

Address: 1013 E UNIVERSITY WY      City: ELLENSBURG    Zip Code: 98926    County: Kittitas  
 Latitude: 47.00224    Longitude: -120.53200    WRIA: 39    Legislative District: 13    Congressional District: 8    TRS: 18N 18E 36

## DETAIL

Status: No Further Action      NFA Received? Yes      Is PSI site? No  
 Statute: MTCA      NFA Date: 8/27/2020      Current VCP? No    Past VCP? Yes  
 Site Rank: 2 - Moderate-High Risk      NFA Reason: Voluntary Cleanup Program Review      Brownfield? No  
 Site Manager: Mefford, John      Responsible Unit: Central      Active Institutional Control? No

## CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Kens Auto Wash II	Upland	No Further Action Required	CE	Mefford, John	Standard Voluntary Cleanup

## ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

## AFFECTED MEDIA & CONTAMINANTS

### MEDIA

Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Benzene	RB	RB				
Lead	RB	RB				
Petroleum-Gasoline	RB	RB				

### Key:

B - Below Cleanup Level      C - Confirmed Above Cleanup Level      RA - Remediated-Above  
 S - Suspected      R - Remediated      RB - Remediated-Below

## SITE ACTIVITIES

Activity	Status	Start Date	End Date/Completion Date
Order/Decree/Amendment	Completed	1/1/1900	9/4/2013
Initial Investigation / Federal Preliminary Assessment	Completed		6/27/1996
Site Discovery/Release Report Received	Completed		6/27/1996
LUST - Notification	Completed		6/27/1996
LUST - Site Characterization Report	Completed		6/27/1996
Early Notice Letter(s)	Completed		9/23/1996
Site Hazard Assessment/Federal Site Inspection	Completed	11/11/1996	1/16/1997
Hazardous Sites Listing/NPL	Completed		11/12/1996

<b>SITE ACTIVITIES</b>			
<b>Activity</b>	<b>Status</b>	<b>Start Date</b>	<b>End Date/ Completion Date</b>
Routine Cleanup	Canceled	2/1/1998	4/2/2002
LUST - Report Received	Completed		7/10/1998
LUST - Report Received	Completed		7/27/1998
LUST - Report Received	Completed		11/17/1998
LUST - Report Received	Completed		2/2/1999
LUST - Report Received	Completed		2/3/1999
VCP Opinion on Remedial Investigation	Completed	12/17/1999	5/24/2000
LUST - Report Received	Completed		4/12/2000
LUST - Report Received	Completed		7/28/2000
LUST - Report Received	Completed		4/29/2002
LUST - Report Received	Completed		7/17/2002
LUST - Report Received	Completed		12/19/2002
LUST - Report Received	Completed		1/14/2003
Remedial Investigation and/or Feasibility Study	Completed	10/10/2003	12/22/2006
LUST - Report Received	Completed		12/10/2003
LUST - Report Received	Completed		1/14/2004
LUST - Report Received	Completed		1/14/2004
LUST - Report Received	Completed		1/14/2004
LUST - Report Received	Completed		9/2/2004
Cleanup Action Plan	Canceled	10/1/2004	8/9/2013
LUST - Report Received	Completed		1/10/2005
LUST - Report Received	Completed		1/24/2005
LUST - Report Received	Completed		2/14/2005
LUST - Report Received	Completed		5/24/2005
LUST - Report Received	Completed		12/15/2005
LUST - Report Received	Completed		8/17/2006
LUST - Report Received	Completed		9/13/2007
LUST - Report Received	Completed		8/20/2008
LUST - Report Received	Completed		4/9/2009
LUST - Report Received	Completed		2/17/2010
LUST - Report Received	Completed		4/25/2011
LUST - Report Received	Completed		5/18/2012
Interim Action - Performance Monitoring	Completed	8/27/2013	2/23/2016
Order/Decree/Amendment	Completed	9/4/2013	4/23/2018
Interim Action - Plan	Completed	12/23/2013	1/23/2014

# Cleanup Site Details

Cleanup Site ID: 5208

<b>SITE ACTIVITIES</b>			
<b>Activity</b>	<b>Status</b>	<b>Start Date</b>	<b>End Date/ Completion Date</b>
Interim Action - Construction	Completed	3/23/2014	2/18/2015
LUST - Report Received	Completed		1/20/2015
LUST - Report Received	Completed		1/20/2015
Monitoring	Completed	6/27/2016	3/5/2018
LUST - Report Received	Completed		8/8/2016
LUST - Report Received	Completed		10/24/2016
LUST - Report Received	Completed		3/6/2017
LUST - Report Received	Completed		10/1/2018
VCP Opinion on Site Cleanup Plan	Completed	10/10/2018	12/19/2018
VCP Technical Assistance	Completed		11/14/2018
LUST - Report Received	Completed		12/20/2018
VCP Opinion on Site Cleanup	Completed	9/24/2019	4/9/2020
LUST - Site Assessment Report	Completed		9/26/2019
LUST - Report Received	Completed		3/3/2020
Petroleum Impacts to Groundwater Model Remedies	Completed		4/9/2020
Remove site from Hazardous Sites List	Completed		8/27/2020
Site Status Changed to NFA	Completed		8/27/2020