

Cleanup Site Details

Cleanup Site ID: 5208

Cleanup Site ID: 5208 Facility/Site ID: 3892 UST ID: 4099 [Site Page](#) [Site Documents](#) [View Map](#)

Cleanup Site Name: Kens Auto Wash II [Glossary](#)

Alternate Names: KENS AUTO WASH II

LOCATION

Address: 1013 E UNIVERSITY WY City: ELLENSBURG Zip Code: 98926 County: Kittitas
Latitude: 47.00224 Longitude: -120.53200 WRIA: 39 Legislative District: 13 Congressional District: 8 TRS: 18N 18E 36

DETAIL

Status: No Further Action NFA Received? Yes Is PSI site? No
Statute: MTCA NFA Date: 8/27/2020 Current VCP? No Past VCP? Yes
Site Rank: 2 - Moderate-High Risk NFA Reason: Voluntary Cleanup Program Review Brownfield? No
Site Manager: Mefford, John Responsible Unit: Central Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Kens Auto Wash II	Upland	No Further Action Required	CE	Mefford, John	Standard Voluntary Cleanup

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Benzene	RB	RB				
Lead	RB	RB				
Petroleum-Gasoline	RB	RB				

Key:
B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Order/Decree/Amendment	Completed	1/1/1900	9/4/2013
Initial Investigation / Federal Preliminary Assessment	Completed		6/27/1996
Site Discovery/Release Report Received	Completed		6/27/1996
LUST - Notification	Completed		6/27/1996
LUST - Site Characterization Report	Completed		6/27/1996
Early Notice Letter(s)	Completed		9/23/1996
Site Hazard Assessment	Completed	11/11/1996	1/16/1997
Hazardous Sites Listing	Completed		11/12/1996

Cleanup Site Details

Cleanup Site ID: 5208

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
LUST - Report Received	Completed		7/10/1998
LUST - Report Received	Completed		7/27/1998
LUST - Report Received	Completed		11/17/1998
LUST - Report Received	Completed		2/2/1999
LUST - Report Received	Completed		2/3/1999
VCP Opinion on Remedial Investigation	Completed	12/17/1999	5/24/2000
LUST - Report Received	Completed		4/12/2000
LUST - Report Received	Completed		7/28/2000
LUST - Report Received	Completed		4/29/2002
LUST - Report Received	Completed		7/17/2002
LUST - Report Received	Completed		12/19/2002
LUST - Report Received	Completed		1/14/2003
Remedial Investigation and/or Feasibility Study	Completed	10/10/2003	12/22/2006
LUST - Report Received	Completed		12/10/2003
LUST - Report Received	Completed		1/14/2004
LUST - Report Received	Completed		1/14/2004
LUST - Report Received	Completed		1/14/2004
LUST - Report Received	Completed		9/2/2004
Cleanup Action Plan	Canceled	10/1/2004	8/9/2013
LUST - Report Received	Completed		1/10/2005
LUST - Report Received	Completed		1/24/2005
LUST - Report Received	Completed		2/14/2005
LUST - Report Received	Completed		5/24/2005
LUST - Report Received	Completed		12/15/2005
LUST - Report Received	Completed		8/17/2006
LUST - Report Received	Completed		9/13/2007
LUST - Report Received	Completed		8/20/2008
LUST - Report Received	Completed		4/9/2009
LUST - Report Received	Completed		2/17/2010
LUST - Report Received	Completed		4/25/2011
LUST - Report Received	Completed		5/18/2012
Interim Action - Performance Monitoring	Completed	8/27/2013	2/23/2016
Order/Decree/Amendment	Completed	9/4/2013	4/23/2018
Interim Action - Plan	Completed	12/23/2013	1/23/2014
Interim Action - Construction	Completed	3/23/2014	2/18/2015

Cleanup Site Details

Cleanup Site ID: 5208

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
LUST - Report Received	Completed		1/20/2015
LUST - Report Received	Completed		1/20/2015
Monitoring	Completed	6/27/2016	3/5/2018
LUST - Report Received	Completed		8/8/2016
LUST - Report Received	Completed		10/24/2016
LUST - Report Received	Completed		3/6/2017
LUST - Report Received	Completed		10/1/2018
VCP Opinion on Site Cleanup Plan	Completed	10/10/2018	12/19/2018
VCP Technical Assistance	Completed		11/14/2018
LUST - Report Received	Completed		12/20/2018
VCP Opinion on Site Cleanup	Completed	9/24/2019	4/9/2020
LUST - Site Assessment Report	Completed		9/26/2019
LUST - Report Received	Completed		3/3/2020
Petroleum Impacts to Groundwater Model Remedies	Completed		4/9/2020
Remove site from Hazardous Sites List	Completed		8/27/2020
Site Status Changed to NFA	Completed		8/27/2020