

Cleanup Site Details

Cleanup Site ID: 5208

Cleanup Site ID: 5208	Facility/Site ID: 3892	UST ID: 4099	Site Page	Site Documents	View Map	
Cleanup Site Name: Kens Auto Wash II					Glossary	
Alternate Names: KENS AUTO WASH II						
LOCATION						
Address: 1013 E UNIVERSITY WY		City: ELLENSBURG	Zip Code: 98926	County: Kittitas		
Latitude: 47.00224	Longitude: -120.53200	WRIA: 39	Legislative District: 13	Congressional District: 8	TRS: 18N 18E 36	
DETAIL						
Status: No Further Action	NFA Received? Yes	Is PSI site? No				
Statute: MTCA	NFA Date: 8/27/2020	Current VCP? No	Past VCP? Yes			
Site Rank: 2 - Moderate-High Risk	NFA Reason: Voluntary Cleanup Program Review	Brownfield? No				
Site Manager: Mefford, John	Responsible Unit: Central	Active Institutional Control? No				
CLEANUP UNITS						
Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process	
Kens Auto Wash II	Upland	No Further Action Required	CE	Mefford, John	Standard Voluntary Cleanup	
ACTIVE INSTITUTIONAL CONTROLS						
Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
There are no current Institutional Controls in effect for this site.						
AFFECTED MEDIA & CONTAMINANTS						
MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Benzene	RB	RB				
Lead	RB	RB				
Petroleum-Gasoline	RB	RB				
Key: B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above S - Suspected R - Remediated RB - Remediated-Below						
SITE ACTIVITIES						
Activity	Status		Start Date	End Date/ Completion Date		
Initial Investigation / Federal Preliminary Assessment	Completed			6/27/1996		
Site Discovery/Release Report Received	Completed			6/27/1996		
LUST - Notification	Completed			6/27/1996		
LUST - Site Characterization Report	Completed			6/27/1996		
Early Notice Letter(s)	Completed			9/23/1996		
Site Hazard Assessment/Federal Site Inspection	Completed		11/11/1996	1/16/1997		
Hazardous Sites Listing/NPL	Completed			11/12/1996		
Routine Cleanup	Canceled		2/1/1998	4/2/2002		
Toxics Cleanup Program		Report Generated: 4/28/2024		Page 1 of 3		

Cleanup Site Details

Cleanup Site ID: 5208

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
LUST - Report Received	Completed		7/10/1998
LUST - Report Received	Completed		7/27/1998
LUST - Report Received	Completed		11/17/1998
LUST - Report Received	Completed		2/2/1999
LUST - Report Received	Completed		2/3/1999
VCP Opinion on Remedial Investigation	Completed	12/17/1999	5/24/2000
LUST - Report Received	Completed		4/12/2000
LUST - Report Received	Completed		7/28/2000
LUST - Report Received	Completed		4/29/2002
LUST - Report Received	Completed		7/17/2002
LUST - Report Received	Completed		12/19/2002
LUST - Report Received	Completed		1/14/2003
Remedial Investigation and/or Feasibility Study	Completed	10/10/2003	12/22/2006
LUST - Report Received	Completed		12/10/2003
LUST - Report Received	Completed		1/14/2004
LUST - Report Received	Completed		1/14/2004
LUST - Report Received	Completed		1/14/2004
LUST - Report Received	Completed		9/2/2004
Cleanup Action Plan	Canceled	10/1/2004	8/9/2013
LUST - Report Received	Completed		1/10/2005
LUST - Report Received	Completed		1/24/2005
LUST - Report Received	Completed		2/14/2005
LUST - Report Received	Completed		5/24/2005
LUST - Report Received	Completed		12/15/2005
LUST - Report Received	Completed		8/17/2006
LUST - Report Received	Completed		9/13/2007
LUST - Report Received	Completed		8/20/2008
LUST - Report Received	Completed		4/9/2009
LUST - Report Received	Completed		2/17/2010
LUST - Report Received	Completed		4/25/2011
LUST - Report Received	Completed		5/18/2012
Interim Action - Performance Monitoring	Completed	8/27/2013	2/23/2016
Order/Decree/Amendment	Completed		9/4/2013
Order/Decree/Amendment	Completed	9/4/2013	4/23/2018
Interim Action - Plan	Completed	12/23/2013	1/23/2014

Cleanup Site Details

Cleanup Site ID: 5208

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
Interim Action - Construction	Completed	3/23/2014	2/18/2015
LUST - Report Received	Completed		1/20/2015
LUST - Report Received	Completed		1/20/2015
Monitoring	Completed	6/27/2016	3/5/2018
LUST - Report Received	Completed		8/8/2016
LUST - Report Received	Completed		10/24/2016
LUST - Report Received	Completed		3/6/2017
LUST - Report Received	Completed		10/1/2018
VCP Opinion on Site Cleanup Plan	Completed	10/10/2018	12/19/2018
VCP Technical Assistance	Completed		11/14/2018
LUST - Report Received	Completed		12/20/2018
VCP Opinion on Site Cleanup	Completed	9/24/2019	4/9/2020
LUST - Site Assessment Report	Completed		9/26/2019
LUST - Report Received	Completed		3/3/2020
Petroleum Impacts to Groundwater Model Remedies	Completed		4/9/2020
Remove site from Hazardous Sites List	Completed		8/27/2020
Site Status Changed to NFA	Completed		8/27/2020