

Cleanup Site Details

Cleanup Site ID: 5210

Cleanup Site ID: 5210 Facility/Site ID: 4380 UST ID: 5821 Site Page Site Documents View Map

Cleanup Site Name: Automotive Services Inc

Alternate Names: ASI CARWASH DIESEL CONTAMINATION, Automotive Services Inc, AUTOMOTIVE SERVICES INC DIESEL RELEASE,

VANCOUVER PORT

LOCATION

Address: 2327 W MILL PLAIN BLVD City: VANCOUVER Zip Code: 98660 County: Clark

Latitude: 45.63754 Longitude: -122.69514 WRIA: 28 Legislative District: 49 Congressional District: 3 TRS: 2N 1E 53

DETAIL

Status: No Further Action NFA Received? Yes Is PSI site? No

Statute: MTCA NFA Date: 3/7/2014 Current VCP? No Past VCP? Yes

Site Rank: N/A NFA Reason: Voluntary Cleanup Program Review Brownfield? No

Site Manager: Gibson, Danielle Responsible Unit: Southwest Active Institutional Control? Yes

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
AUTOMOTIVE SERVICES INC	Upland	No Further Action Required	SW	Gibson, Danielle	Standard Voluntary Cleanup

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
Environmental Covenant	Soil	Restrict Land Use	12/26/2001	3407456	Clark	059115-068
Amended Environmental Covenant	Groundwater	Restrict Land Use, Restrict All Ground Water Extraction/Well Installation, Prohibit Soil Disturbance	9/18/2013	5015545 COV	Clark	059115-068

Institutional Control documents may be available under the 'Site Documents' link at the top of the page. For more details on Institutional Controls, please see the **Environmental Covenants Registry List**.

AFFECTED MEDIA & CONTAMINANTS

	MEDIA					
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Petroleum-Diesel	RA	RA				
Petroleum-Other	RA	RA				

Key:

B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
LUST - Notification	Completed		6/19/1991
LUST - Report Received	Completed		9/16/1991
LUST - Report Received	Completed		11/28/1994
Site Discovery/Release Report Received	Completed		1/9/1996
Initial Investigation / Federal Preliminary Assessment	Completed		3/26/1996
LUST - Report Received	Completed		11/30/1996

Toxics Cleanup Program Report Generated: 11/19/2025 Page 1 of 2



Cleanup Site Details

ECOLOGY State of Washington Cleanup	Cleanup Site Details clean		nup Site ID: 5210				
SITE ACTIVITIES							
Activity	Status	Start Date	End Date/ Completion Date				
Early Notice Letter(s)	Completed		1/10/1997				
Routine Cleanup	Completed	2/1/1997	12/31/1998				
VCP Opinion on Remedial Investigation Work Plan	Completed	9/3/1998	12/26/2001				
Site Discovery/Release Report Received	Completed		1/18/1999				
VCP Opinion on Remedial Investigation	Completed	8/1/2000	12/26/2001				
VCP Opinion on Remedial Investigation Work Plan	Completed	7/22/2006	9/19/2006				
VCP Receipt of Plan or Report	Completed		4/11/2011				
VCP Receipt of Plan or Report	Completed		6/25/2012				
VCP Opinion on Site Cleanup	Completed	9/23/2013	3/7/2014				
Site Status Changed to NFA	Completed		3/7/2014				
Non-LUST Ind Report Received	Completed		2/14/2020				
Periodic Review	Completed	3/2/2020	7/7/2020				
Monitoring	Completed	12/30/2022	6/6/2024				
Periodic Review	Planned	3/1/2025	7/6/2025				