

Cleanup Site ID: 5252

Cleanup Site Details

Facility/Site ID: 1436359 UST ID: 7972 Site Page Site Documents View Map

Cleanup Site ID: 5252

Cleanup Site Name: Newmans Chevron

Alternate Names: 6th Street Fuel, NEWMANS CHEVRON

LOCATION

Address: 2021 6TH ST City: BREMERTON Zip Code: 98337 County: Kitsap

Latitude: 47.56707 Longitude: -122.64572 WRIA: 15 Legislative District: 26 Congressional District: 6 TRS: 24N 1E 14

DETAIL

Status: Cleanup Started NFA Received? No Is PSI site? No

Statute: MTCA NFA Date: N/A Current VCP? No Past VCP? Yes

Site Rank: 5 - Lowest Assessed Risk NFA Reason: N/A Brownfield? No

Site Manager: Myers, Dale R Responsible Unit: Northwest Active Institutional Control? No

CLEANUP UNITS

 Cleanup Unit Name
 Unit Type
 Unit Status
 Resp Unit
 Unit Manager
 Current Process

 Newmans Chevron
 Upland
 Cleanup Started
 NW
 Myers, Dale R
 Ecology-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type Restriction Media Restrictions/Requirements Date Recording Number County Tax Parcel

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

	MEDIA					
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Benzene	С					
Non-Halogenated Solvents	С					
Petroleum-Gasoline	С					
Petroleum-Other	С					

Key:

B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
LUST - Notification	Completed		8/9/1990
VCP Opinion on Cleanup Action	Completed	3/3/2001	10/22/2003
LUST - Report Received	Completed		3/26/2001
LUST - Report Received	Completed		8/20/2009
Site Hazard Assessment/Federal Site Inspection	Completed	8/27/2009	2/15/2010
Hazardous Sites Listing/NPL	Completed		2/15/2010
Order/Decree/Amendment	In Process	10/26/2017	

Toxics Cleanup Program Report Generated: 4/28/2024 Page 1 of 2



Cleanup Site Details

SITE ACTIVITIES						
Activity	Status	Start Date	End Date/ Completion Date			
Remedial Investigation and/or FS Work Plan	Completed		9/10/2018			
Remedial Investigation and/or Feasibility Study	In Process	9/10/2018				

Cleanup Site ID: 5252