

Cleanup Site Details

Cleanup Site ID: 5252

Cleanup Site ID: 5252
Facility/Site ID: 1436359
UST ID: 7972
[Site Page](#)
[Site Documents](#)
[View Map](#)
Cleanup Site Name: Newmans Chevron
[Glossary](#)
Alternate Names: 6th Street Fuel, NEWMANS CHEVRON

LOCATION

Address: 2021 6TH ST
City: BREMERTON
Zip Code: 98337
County: Kitsap
Latitude: 47.56707
Longitude: -122.64572
WRIA: 15
Legislative District: 26
Congressional District: 6
TRS: 24N 1E 14

DETAIL

Status: Cleanup Started
NFA Received? No
Is PSI site? No
Statute: MTCA
NFA Date: N/A
Current VCP? No
Past VCP? Yes
Site Rank: 5 - Lowest Assessed Risk
NFA Reason: N/A
Brownfield? No
Site Manager: Myers, Dale R
Responsible Unit: Northwest
Active Institutional Control? No

CLEANUP UNITS

| Cleanup Unit Name | Unit Type | Unit Status | Resp Unit | Unit Manager | Current Process |
|-------------------|-----------|-----------------|-----------|---------------|---------------------------------|
| Newmans Chevron | Upland | Cleanup Started | NW | Myers, Dale R | Ecology-supervised or conducted |

ACTIVE INSTITUTIONAL CONTROLS

| Instrument Type | Restriction Media | Restrictions/Requirements | Date | Recording Number | Recording County | Tax Parcel |
|-----------------|-------------------|---------------------------|------|------------------|------------------|------------|
|-----------------|-------------------|---------------------------|------|------------------|------------------|------------|

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

MEDIA

| Contaminant | Soil | Groundwater | Surface Water | Sediment | Air | Bedrock |
|--------------------------|------|-------------|---------------|----------|-----|---------|
| Benzene | C | | | | | |
| Non-Halogenated Solvents | C | | | | | |
| Petroleum-Gasoline | C | | | | | |
| Petroleum-Other | C | | | | | |

Key:
B - Below Cleanup Level
C - Confirmed Above Cleanup Level
RA - Remediated-Above
S - Suspected
R - Remediated
RB - Remediated-Below

SITE ACTIVITIES

| Activity | Status | Start Date | End Date/Completion Date |
|------------------------------------------------|------------|------------|--------------------------|
| LUST - Notification | Completed | | 8/9/1990 |
| VCP Opinion on Cleanup Action | Completed | 3/3/2001 | 10/22/2003 |
| LUST - Report Received | Completed | | 3/26/2001 |
| LUST - Report Received | Completed | | 8/20/2009 |
| Site Hazard Assessment/Federal Site Inspection | Completed | 8/27/2009 | 2/15/2010 |
| Hazardous Sites Listing/NPL | Completed | | 2/15/2010 |
| Order/Decree/Amendment | In Process | 10/26/2017 | |

Cleanup Site Details

Cleanup Site ID: 5252

| SITE ACTIVITIES | | | |
|-------------------------------------------------|---------------|-------------------|--------------------------------------|
| Activity | Status | Start Date | End Date/ Completion Date |
| Remedial Investigation and/or FS Work Plan | Completed | | 9/10/2018 |
| Remedial Investigation and/or Feasibility Study | In Process | 9/10/2018 | |