

Cleanup Site Details

Cleanup Site ID: 536

Cleanup Site ID: 536	Facility/Site ID: 199	UST ID: 2837	Site Page	Site Documents	View Map
Cleanup Site Name: US DOE BPA Ross Complex					Glossary
Alternate Names: BPA ROSS COMPLEX, Ross Complex, US BPA ROSS COMPLEX, US DOE BPA Ross Complex					

LOCATION

Address: 5411 NE HWY 99			City: VANCOUVER	Zip Code: 98666	County: Clark
Latitude: 45.66188	Longitude: -122.66520	WRIA: 28	Legislative District: 49	Congressional District: 3	TRS: 2N 1E 15

DETAIL

Status: No Further Action	NFA Received? Yes	Is PSI site? No
Statute: Federal - CERCLA	NFA Date: 1/27/1996	Current VCP? No Past VCP? No
Site Rank: 0 - NPL Site (Fed HRS Score)	NFA Reason: Federal Supervised/Conducted Cleanup	Brownfield? No
Site Manager: Rogowski, Barry	Responsible Unit: EPA	Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
ROSS COMPLEX	Upland	No Further Action Required	EPA	Rogowski, Barry	Federal-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Metals Priority Pollutants	R					

Key:
 B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
 S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Site Discovery/Release Report Received	Completed		7/1/1993
National Priorities Listing	Completed		8/31/1993
Remove site from Hazardous Sites List	Completed		1/27/1996
Site Status Changed to NFA	Completed		1/27/1996