

Cleanup Site Details

Cleanup Site ID: 536

Cleanup Site ID: 536 Facility/Site ID: 199 UST ID: 2837 [Site Page](#) [Site Documents](#) [View Map](#)

Cleanup Site Name: US DOE BPA Ross Complex [Glossary](#)

Alternate Names: BPA ROSS COMPLEX, Ross Complex, US BPA ROSS COMPLEX, US DOE BPA Ross Complex

LOCATION

Address: 5411 NE HWY 99 City: VANCOUVER Zip Code: 98666 County: Clark
 Latitude: 45.66188 Longitude: -122.66520 WRIA: 28 Legislative District: 49 Congressional District: 3 TRS: 2N 1E 15

DETAIL

Status: No Further Action NFA Received? Yes Is PSI site? No
 Statute: Federal - CERCLA NFA Date: 1/27/1996 Current VCP? No Past VCP? No
 Site Rank: 0 - NPL Site (Fed HRS Score) NFA Reason: Federal Supervised/Conducted Cleanup Brownfield? No
 Site Manager: Rogowski, Barry Responsible Unit: EPA Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
ROSS COMPLEX	Upland	No Further Action Required	EPA	Rogowski, Barry	Federal-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

Contaminant	MEDIA					
	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Metals Priority Pollutants	R					

Key:
 B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
 S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Site Discovery/Release Report Received	Completed		7/1/1993
Hazardous Sites Listing/NPL	Completed		8/31/1993
Remove site from Hazardous Sites List	Completed		1/27/1996
Site Status Changed to NFA	Completed		1/27/1996