

# Cleanup Site Details

Cleanup Site ID: 54

Cleanup Site ID: 54      Facility/Site ID: 2071      UST ID: 1429      [Site Page](#)      [Site Documents](#)      [View Map](#)

Cleanup Site Name: Duwamish Shipyard      [Glossary](#)

Alternate Names: Alaska Marine Lines, DUWAMISH SHIPYARD, DUWAMISH SHIPYARD INC, Seattle Machine Works Inc Marginal Way

**LOCATION**

Address: 5658 W MARGINAL WAY SW      City: SEATTLE      Zip Code: 98106      County: King  
 Latitude: 47.55056      Longitude: -122.34251      WRIA: 9      Legislative District: 34      Congressional District: 7      TRS: 24N 4E 19

**DETAIL**

Status: Cleanup Started      NFA Received? No      Is PSI site? No  
 Statute: MTCA      NFA Date: N/A      Current VCP? No      Past VCP? No  
 Site Rank: 2 - Moderate-High Risk      NFA Reason: N/A      Brownfield? No  
 Site Manager: Nale, Cliff      Responsible Unit: Northwest      Active Institutional Control? No

**CLEANUP UNITS**

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Duwamish Shipyard	Sediment	Cleanup Started	NW	Nale, Cliff	Ecology-supervised or conducted
Duwamish Shipyard	Upland	Cleanup Started	NW	Nale, Cliff	Ecology-supervised or conducted

**ACTIVE INSTITUTIONAL CONTROLS**

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

**AFFECTED MEDIA & CONTAMINANTS**

Contaminant	MEDIA					
	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Base/Neutral/Acid Organics	C			S		
Benzene	C					
Halogenated Organics				S		
Metals - Other				S		
Metals Priority Pollutants	R	C		C		
Non-Halogenated Solvents	C	C				
Organotins				C		
Petroleum Products-Unspecified	C	C				
Petroleum-Diesel	C					
Petroleum-Gasoline	C					
Polychlorinated biPhenyls (PCB)	B	B		C		
Polycyclic Aromatic Hydrocarbons	C	B		C		

**Key:**  
 B - Below Cleanup Level      C - Confirmed Above Cleanup Level      RA - Remediated-Above  
 S - Suspected      R - Remediated      RB - Remediated-Below

# Cleanup Site Details

Cleanup Site ID: 54

<b>SITE ACTIVITIES</b>			
<b>Activity</b>	<b>Status</b>	<b>Start Date</b>	<b>End Date/ Completion Date</b>
Site Discovery/Release Report Received	Completed		3/1/1988
LUST - Notification	Completed		7/12/2000
LUST - Report Received	Completed		10/11/2000
Site Hazard Assessment/Federal Site Inspection	Completed	3/24/2006	2/14/2007
LUST - Report Received	Completed		8/25/2006
Hazardous Sites Listing/NPL	Completed		2/14/2007
LUST - Report Received	Completed		9/28/2008
Order/Decree/Amendment	In Process	6/1/2009	
Remedial Investigation and/or Feasibility Study	Canceled	6/1/2009	2/28/2016
Remedial Investigation and/or Feasibility Study	Completed	4/5/2019	5/20/2019
Remedial Investigation and/or Feasibility Study	In Process	8/10/2020	