

Cleanup Site ID: 54

Cleanup Site Details

Facility/Site ID: 2071 **UST ID:** 1429 Site Page **Site Documents** View Map

Cleanup Site ID: 54

Cleanup Site Name: Duwamish Shipyard **Glossary**

Alternate Names: Alaska Marine Lines, DUWAMISH SHIPYARD, DUWAMISH SHIPYARD INC, Seattle Machine Works Inc Marginal Way

LOCATION

Address: 5658 W MARGINAL WAY SW City: SEATTLE **Zip Code:** 98106 County: King

Latitude: 47.55056 Longitude: -122.34251 WRIA: 9 Legislative District: 34 Congressional District: 7 **TRS**: 24N 4E 19

DETAIL

NFA Received? No Is PSI site? Status: Cleanup Started No

MTCA NFA Date: Current VCP? Past VCP? No Statute: N/A No

NFA Reason: Site Rank: 2 - Moderate-High Risk N/A Brownfield?

Site Manager: Nale, Cliff Responsible Unit: Northwest **Active Institutional Control?** No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Duwamish Shipyard	Sediment	Cleanup Started	NW	Nale, Cliff	Ecology-supervised or conducted
Duwamish Shipyard	Upland	Cleanup Started	NW	Nale, Cliff	Ecology-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	----------------------	---------------------------	------	---------------------	---------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

	MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock	
Base/Neutral/Acid Organics	С			S			
Benzene	С						
Halogenated Organics				S			
Metals - Other				S			
Metals Priority Pollutants	R	С		С			
Non-Halogenated Solvents	С	С					
Organotins				С			
Petroleum Products-Unspecified	С	С					
Petroleum-Diesel	С						
Petroleum-Gasoline	С						
Polychlorinated biPhenyls (PCB)	В	В		С			
Polycyclic Aromatic Hydrocarbons	С	В		С			

B - Below Cleanup Level C - Confirmed Above Cleanup Level S - Suspected

R - Remediated

RA - Remediated-Above RB - Remediated-Below

Toxics Cleanup Program Report Generated: 7/24/2025 Page 1 of 2



Cleanup Site Details

Cleanup Site ID: 54

SITE ACTIVITIES						
Activity	Status	Start Date	End Date/ Completion Date			
Site Discovery/Release Report Received	Completed		3/1/1988			
LUST - Notification	Completed		7/12/2000			
LUST - Report Received	Completed		10/11/2000			
Site Hazard Assessment	Completed	3/24/2006	2/14/2007			
LUST - Report Received	Completed		8/25/2006			
Hazardous Sites Listing	Completed		2/14/2007			
LUST - Report Received	Completed		9/28/2008			
Order/Decree/Amendment	In Process	6/1/2009				
Remedial Investigation and/or Feasibility Study	Canceled	6/1/2009	2/28/2016			
Remedial Investigation and/or Feasibility Study	Completed	4/5/2019	5/20/2019			
Remedial Investigation and/or Feasibility Study	In Process	8/10/2020				