

Cleanup Site Details

Cleanup Site ID: 5403

Cleanup Site ID: 5403 Facility/Site ID: 6261637 UST ID: 3408 Site Page Site Documents View Map

Cleanup Site Name: Pederson Fryer Farms Inc

Alternate Names: Pederson Fryer Farms Inc, PEDERSONS FRYER FARMS INC

LOCATION

Address: 2901 72nd St E City: Tacoma Zip Code: 98404 County: Pierce

Latitude: 47.19190 Longitude: -122.39083 WRIA: 10 Legislative District: 25 Congressional District: 10 TRS: 20N 3E 26

DETAIL

Status: Cleanup Started NFA Received? No Is PSI site? No

Statute: MTCA NFA Date: N/A Current VCP? No Past VCP? Yes

Site Rank: N/A NFA Reason: N/A Brownfield? No

Site Manager: Southwest Region Responsible Unit: Southwest Active Institutional Control? No

CLEANUP UNITS

 Cleanup Unit Name
 Unit Type
 Unit Status
 Resp Unit
 Unit Manager
 Current Process

 PEDERSON'S FRYER FARMS
 Upland
 Cleanup Started
 SW
 Southwest Region
 Ecology-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type Restriction Media Restrictions/Requirements Date Recording Number County Tax Parcel

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

	MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock	
Petroleum-Other	С	С					

Key:

B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
LUST - Report Received	Completed		11/28/1994
LUST - Notification	Completed		12/2/1994
LUST - Site Characterization Report	Completed		12/20/1996
LUST - Report Received	Completed		7/27/1998
Site Discovery/Release Report Received	Completed		1/16/2001
LUST - Report Received	Completed		1/16/2001
LUST - Report Received	Completed		1/16/2001
LUST - Report Received	Completed		1/16/2001
LUST - Report Received	Completed		1/16/2001
VCP Opinion on Interim Action	Canceled	1/16/2001	1/1/1900

Toxics Cleanup Program Report Generated: 8/24/2025 Page 1 of 2



Cleanup Site Details

SITE ACTIVITIES					
vity Status		Start Date	End Date/ Completion Date		
LUST - Site Assessment Report	Completed		10/1/2001		
LUST - Report Received	Completed		7/7/2003		
LUST - Site Characterization Report	Completed		9/18/2003		
LUST - Report Received	Completed		1/15/2004		
LUST - Report Received	Completed		8/20/2004		
LUST - Site Characterization Report	Completed		10/28/2004		
LUST - Report Received	Completed		11/10/2004		
LUST - Report Received	Completed		3/10/2005		
LUST - Report Received	Completed		6/21/2005		
LUST - Report Received	Completed		10/7/2005		
Remedial Investigation and/or Feasibility Study	Completed	10/31/2010	9/29/2011		
Remedial Investigation and/or FS Work Plan	Completed	3/7/2011	3/28/2011		
Interim Action - Construction	Completed	5/30/2011	6/30/2011		
Remedial Investigation and/or Feasibility Study	Completed	9/29/2011	5/10/2012		
Cleanup Action Plan	Completed	5/10/2012	7/9/2012		
Interim Action - Construction	Planned	1/1/2020	1/1/1900		

Cleanup Site ID: 5403