

Cleanup Site ID: 546

Cleanup Site Details

Facility/Site ID: 23627358 UST ID: 582093 Site Page Site Documents View Map

Cleanup Site ID: 546

Cleanup Site Name: Monroe Auto Salvage Parcel 6 Glossary

Alternate Names: MONROE AUTO SALVAGE PARCEL 6

LOCATION

Address: 426 FREMONT ST City: MONROE Zip Code: 98272 County: Snohomish

Latitude: 47.85482 Longitude: -121.96658 WRIA: 7 Legislative District: 39 Congressional District: 1 TRS: 27N 7E 6

DETAIL

Status: No Further Action NFA Received? Yes Is PSI site? No

Statute: MTCA NFA Date: 12/18/2003 Current VCP? No Past VCP? Yes

Site Rank: N/A NFA Reason: Voluntary Cleanup Program Review Brownfield? No

Site Manager: Aitken, Judy Responsible Unit: Northwest Active Institutional Control? No

CLEANUP UNITS

 Cleanup Unit Name
 Unit Type
 Unit Status
 Resp Unit
 Unit Manager
 Current Process

 Monroe Auto Salvage Parcel 6
 Upland
 No Further Action Required
 NW
 Aitken, Judy
 Standard Voluntary Cleanup

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type Restriction Media Restrictions/Requirements Date Recording Number County Tax Parcel

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

	MEDIA					
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Metals Priority Pollutants	R					
Petroleum Products-Unspecified	R					

Key:

B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
VCP Opinion on Cleanup Action	Completed	7/2/1999	12/18/2003
Site Status Changed to NFA	Completed		12/18/2003

Toxics Cleanup Program Report Generated: 5/29/2025 Page 1 of 1