

## Cleanup Site Details

Cleanup Site ID: 5510

Cleanup Site ID: 5510 Facility/Site ID: 9997635 UST ID: 1801 Site Page Site Documents View Map

Cleanup Site Name: Orondo Elementary School

Alternate Names: ORONDO ELEMENTARY SCHOOL, Orondo Elementary School LUST

LOCATION

Address: 100 ORONDO SCHOOL RD City: ORONDO Zip Code: 98843 County: Douglas

Latitude: 47.64104 Longitude: -120.21681 WRIA: 44 Legislative District: 12 Congressional District: 4 TRS: 25N 21E 28

**DETAIL** 

Status: No Further Action NFA Received? Yes Is PSI site? No

Statute: MTCA NFA Date: 10/3/2008 Current VCP? No Past VCP? No

Site Rank: 4 - Low-Moderate Risk NFA Reason: Ecology Supervised/Conducted Brownfield? No

Cleanup

Site Manager: Dunbar, Mark Responsible Unit: Central Active Institutional Control? Yes

**CLEANUP UNITS** 

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Orondo Elementary School	Upland	No Further Action Required	CE	Central Region	Ecology-supervised or conducted

#### **ACTIVE INSTITUTIONAL CONTROLS**

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
Environmental Covenant	Soil	Restrict Access, Prohibit Soil Disturbance	7/2/2008	3125344	Douglas	75702000000; 75701900001

Institutional Control documents may be available under the 'Site Documents' link at the top of the page. For more details on Institutional Controls, please see the **Environmental Covenants Registry List**.

#### **AFFECTED MEDIA & CONTAMINANTS**

	MEDIA					
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Arsenic	RA					
Lead	RA					

Key:

B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above S - Suspected R - Remediated RB - Remediated-Below

### SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Site Discovery/Release Report Received	Completed		8/25/1998
Initial Investigation / Federal Preliminary Assessment	Completed		9/14/2005
Early Notice Letter(s)	Completed		9/23/2005
Site Hazard Assessment/Federal Site Inspection	Completed	12/22/2005	2/2/2007
Hazardous Sites Listing/NPL	Completed		2/2/2007
Interim Action	Completed	3/29/2007	9/30/2007
Remove site from Hazardous Sites List	Completed		10/3/2008
Site Status Changed to NFA	Completed		10/3/2008

Toxics Cleanup Program Report Generated: 5/7/2024 Page 1 of 2



# Cleanup Site Details

Cleanup Site ID: 5510

SITE ACTIVITIES						
Activity	Status	Start Date	End Date/ Completion Date			
Periodic Review	Completed	5/21/2013	7/29/2013			
Periodic Review	Completed	2/21/2018	5/21/2018			
Periodic Review	Planned	4/1/2023	7/31/2023			

Toxics Cleanup Program Report Generated: 5/7/2024 Page 2 of 2