

Cleanup Site ID: 5586

Cleanup Site Details

Facility/Site ID: 15685336 UST ID: 5233 Site Page Site Documents View Map

Cleanup Site ID: 5586

Cleanup Site Name: Chevron 97348

Alternate Names: CHEVRON 97348

LOCATION

Address: 500 and 510 N WENATCHEE AVE City: WENATCHEE Zip Code: 98801 County: Chelan

Latitude: 47.43106 Longitude: -120.31698 WRIA: 45 Legislative District: 12 Congressional District: 8 TRS: 22N 20E 3

DETAIL

Status: No Further Action NFA Received? Yes Is PSI site? No

Statute: MTCA NFA Date: 5/7/2019 Current VCP? No Past VCP? Yes

Site Rank: 2 - Moderate-High Risk NFA Reason: Ecology Supervised/Conducted Brownfield? No

Cleanup

Site Manager: Winslow, Frank Responsible Unit: Central Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Chevron 7348	Upland	No Further Action Required	CE	Winslow, Frank	Ecology-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	----------------------	---------------------------	------	---------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

	MEDIA					
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Petroleum-Diesel	RB	RB				
Petroleum-Gasoline	RB	RB				
Petroleum-Other	RB	RB				

Key:

B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Site Discovery/Release Report Received	Completed		4/30/1991
LUST - Notification	Completed		4/30/1991
LUST - Report Received	Completed		6/6/1991
LUST - Report Received	Completed		7/19/1991
LUST - Report Received	Completed		2/24/1992
LUST - Report Received	Completed		2/24/1992
LUST - Report Received	Completed		5/7/1993

Toxics Cleanup Program Report Generated: 5/16/2024 Page 1 of 3



Cleanup Site Details

Cleanup S	ite ID:	5586
-----------	---------	------

SITE ACTIVITIES				
Activity	Status	Start Date	End Date/ Completion Date	
LUST - Report Received	Completed		11/26/1993	
LUST - Report Received	Completed		11/26/1993	
LUST - Report Received	Completed		2/3/1994	
LUST - Report Received	Completed		5/11/1994	
LUST - Report Received	Completed		4/10/1995	
LUST - Report Received	Completed		5/26/1995	
LUST - Report Received	Completed		10/13/1995	
LUST - Report Received	Completed		12/21/1995	
LUST - Report Received	Completed		10/3/1996	
LUST - Site Characterization Report	Completed		10/19/2001	
LUST - Report Received	Completed		1/22/2002	
LUST - Report Received	Completed		11/4/2002	
LUST - Report Received	Completed		10/6/2003	
LUST - Report Received	Completed		4/22/2004	
LUST - Report Received	Completed		10/5/2004	
LUST - Report Received	Completed		7/5/2005	
VCP Opinion on Interim Action	Completed	1/30/2006	4/25/2006	
LUST - Report Received	Completed		3/13/2006	
LUST - Report Received	Completed		8/28/2006	
LUST - Report Received	Completed		6/18/2007	
LUST - Report Received	Completed		8/6/2007	
LUST - Report Received	Completed		10/11/2007	
LUST - Report Received	Completed		12/17/2007	
LUST - Report Received	Completed		12/19/2007	
LUST - Report Received	Completed		2/1/2008	
LUST - Report Received	Completed		9/26/2008	
LUST - Report Received	Completed		1/15/2009	
LUST - Report Received	Completed		3/25/2009	
LUST - Report Received	Completed		4/23/2009	
LUST - Report Received	Completed		6/22/2011	
Site Hazard Assessment/Federal Site Inspection	Completed	2/20/2014	12/15/2014	
LUST - Report Received	Completed		12/11/2014	
LUST - Report Received	Completed		12/11/2014	
Hazardous Sites Listing/NPL	Completed		1/6/2015	
Order/Decree/Amendment	Completed	11/21/2017	5/7/2019	
Toxics Cleanup Program Report Generated: 5/16/2024			Page 2 of 3	



Cleanup Site Details

SITE ACTIVITIES					
Activity	Status	Start Date	End Date/ Completion Date		
LUST - Report Received	Completed		6/18/2018		
Cleanup - Performance Monitoring	Completed	7/15/2018	4/29/2019		
LUST - Report Received	Completed		11/2/2018		
LUST - Report Received	Completed		11/29/2018		
LUST - Report Received	Completed		12/28/2018		
Remove site from Hazardous Sites List	Completed		4/29/2019		
Site Status Changed to NFA	Completed		5/7/2019		

Cleanup Site ID: 5586