

# Cleanup Site Details

Cleanup Site ID: 5586

<b>Cleanup Site ID:</b> 5586	<b>Facility/Site ID:</b> 15685336	<b>UST ID:</b> 5233	<a href="#">Site Page</a>	<a href="#">Site Documents</a>	<a href="#">View Map</a>
<b>Cleanup Site Name:</b> Chevron 97348					
<b>Alternate Names:</b> CHEVRON 97348					
<b>LOCATION</b>					
<b>Address:</b> 500 and 510 N WENATCHEE AVE		<b>City:</b> WENATCHEE	<b>Zip Code:</b> 98801	<b>County:</b> Chelan	
<b>Latitude:</b> 47.43106	<b>Longitude:</b> -120.31698	<b>WRIA:</b> 45	<b>Legislative District:</b> 12	<b>Congressional District:</b> 8	<b>TRS:</b> 22N 20E 3
<b>DETAIL</b>					
<b>Status:</b> No Further Action	<b>NFA Received?</b> Yes	<b>Is PSI site?</b> No			
<b>Statute:</b> MTCA	<b>NFA Date:</b> 5/7/2019	<b>Current VCP?</b> No		<b>Past VCP?</b> Yes	
<b>Site Rank:</b> 2 - Moderate-High Risk	<b>NFA Reason:</b> Ecology Supervised/Conducted Cleanup	<b>Brownfield?</b> No			
<b>Site Manager:</b> Winslow, Frank	<b>Responsible Unit:</b> Central	<b>Active Institutional Control?</b> No			
<b>CLEANUP UNITS</b>					
<b>Cleanup Unit Name</b>	<b>Unit Type</b>	<b>Unit Status</b>	<b>Resp Unit</b>	<b>Unit Manager</b>	<b>Current Process</b>
Chevron 7348	Upland	No Further Action Required	CE	Winslow, Frank	Ecology-supervised or conducted
<b>ACTIVE INSTITUTIONAL CONTROLS</b>					
<b>Instrument Type</b>	<b>Restriction Media</b>	<b>Restrictions/Requirements</b>	<b>Date</b>	<b>Recording Number</b>	<b>Recording County</b>
There are no current Institutional Controls in effect for this site.					
<b>AFFECTED MEDIA &amp; CONTAMINANTS</b>					
<b>MEDIA</b>					
<b>Contaminant</b>	<b>Soil</b>	<b>Groundwater</b>	<b>Surface Water</b>	<b>Sediment</b>	<b>Air</b>
Petroleum-Diesel	RB	RB			
Petroleum-Gasoline	RB	RB			
Petroleum-Other	RB	RB			
<b>Key:</b> B - Below Cleanup Level      C - Confirmed Above Cleanup Level      RA - Remediated-Above S - Suspected                      R - Remediated                      RB - Remediated-Below					
<b>SITE ACTIVITIES</b>					
<b>Activity</b>	<b>Status</b>	<b>Start Date</b>	<b>End Date/ Completion Date</b>		
Site Discovery/Release Report Received	Completed		4/30/1991		
LUST - Notification	Completed		4/30/1991		
LUST - Report Received	Completed		6/6/1991		
LUST - Report Received	Completed		7/19/1991		
LUST - Report Received	Completed		2/24/1992		
LUST - Report Received	Completed		2/24/1992		
LUST - Report Received	Completed		5/7/1993		
<b>Toxics Cleanup Program</b>					

# Cleanup Site Details

Cleanup Site ID: 5586

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
LUST - Report Received	Completed		11/26/1993
LUST - Report Received	Completed		11/26/1993
LUST - Report Received	Completed		2/3/1994
LUST - Report Received	Completed		5/11/1994
LUST - Report Received	Completed		4/10/1995
LUST - Report Received	Completed		5/26/1995
LUST - Report Received	Completed		10/13/1995
LUST - Report Received	Completed		12/21/1995
LUST - Report Received	Completed		10/3/1996
LUST - Site Characterization Report	Completed		10/19/2001
LUST - Report Received	Completed		1/22/2002
LUST - Report Received	Completed		11/4/2002
LUST - Report Received	Completed		10/6/2003
LUST - Report Received	Completed		4/22/2004
LUST - Report Received	Completed		10/5/2004
LUST - Report Received	Completed		7/5/2005
VCP Opinion on Interim Action	Completed	1/30/2006	4/25/2006
LUST - Report Received	Completed		3/13/2006
LUST - Report Received	Completed		8/28/2006
LUST - Report Received	Completed		6/18/2007
LUST - Report Received	Completed		8/6/2007
LUST - Report Received	Completed		10/11/2007
LUST - Report Received	Completed		12/17/2007
LUST - Report Received	Completed		12/19/2007
LUST - Report Received	Completed		2/1/2008
LUST - Report Received	Completed		9/26/2008
LUST - Report Received	Completed		1/15/2009
LUST - Report Received	Completed		3/25/2009
LUST - Report Received	Completed		4/23/2009
LUST - Report Received	Completed		6/22/2011
Site Hazard Assessment	Completed	2/20/2014	12/15/2014
LUST - Report Received	Completed		12/11/2014
LUST - Report Received	Completed		12/11/2014
Hazardous Sites Listing	Completed		1/6/2015
Order/Decree/Amendment	Completed	11/21/2017	5/7/2019

# Cleanup Site Details

Cleanup Site ID: 5586

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
LUST - Report Received	Completed		6/18/2018
Cleanup - Performance Monitoring	Completed	7/15/2018	4/29/2019
LUST - Report Received	Completed		11/2/2018
LUST - Report Received	Completed		11/29/2018
LUST - Report Received	Completed		12/28/2018
Remove site from Hazardous Sites List	Completed		4/29/2019
Site Status Changed to NFA	Completed		5/7/2019