

Cleanup Site Details

Cleanup Site ID: 5610

Cleanup Site ID: 5610 Facility/Site ID: 17222251 UST ID: 8917 Site Page Site Documents View Map

Cleanup Site Name: Whidbey Marine & Auto Supply

Alternate Names: Whidbey Marine, Whidbey Marine & Auto, WHIDBEY MARINE & AUTO SUPPLY

LOCATION

Address: 1695 MAIN ST City: FREELAND Zip Code: 98249 County: Island

Latitude: 48.00993 Longitude: -122.52366 WRIA: 6 Legislative District: 10 Congressional District: 2 TRS: 29N 2E 11

DETAIL

Status: Cleanup Started NFA Received? No Is PSI site? Yes

Statute: MTCA NFA Date: N/A Current VCP? No Past VCP? Yes

Site Rank: N/A NFA Reason: N/A Brownfield? No

Site Manager: Rapp, John Responsible Unit: Northwest Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Whidbey Marine & Auto Supply	Upland	Cleanup Started	NW	Rapp, John	Ecology-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
	IVIEUIA			Nullibel	County	

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

	MEDIA					
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Benzene	С	С				
Other Non-Halogenated Organics	С	С				
Petroleum-Diesel	С	С				
Petroleum-Gasoline	С	С				

Key:

B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
LUST - Notification	Completed		9/28/2005
Site Discovery/Release Report Received	Completed		9/28/2005
VCP Opinion on Interim Action	Completed	12/7/2005	2/1/2006
VCP Opinion on Interim Action	Completed	3/13/2007	3/19/2007
VCP Opinion on Interim Action	Canceled	7/6/2007	1/1/1900
VCP Opinion on Interim Action	Completed	9/17/2007	9/20/2007
VCP Status Request	Completed	1/13/2010	2/13/2010

Toxics Cleanup Program Report Generated: 8/1/2025 Page 1 of 2



Cleanup Site Details

Cleanup Site ID: 5610

SITE ACTIVITIES						
Activity	Status	Start Date	End Date/ Completion Date			
VCP Opinion on Remedial Investigation	Completed	1/15/2010	1/26/2010			
LUST - Report Received	Completed		5/5/2011			
VCP Opinion on Site Cleanup	Completed	3/7/2013	6/3/2013			
VCP Receipt of Plan or Report	Completed		7/11/2014			
VCP Receipt of Plan or Report	Completed		1/14/2015			
VCP Receipt of Plan or Report	Completed		5/26/2015			
VCP Receipt of Plan or Report	Completed		10/9/2015			
VCP Receipt of Plan or Report	Completed		1/8/2016			
VCP Receipt of Plan or Report	Completed		4/19/2016			
SHARP Assessment	Completed		5/24/2024			