

## Cleanup Site Details

Cleanup Site ID: 5610

Cleanup Site ID: 5610 Facility/Site ID: 17222251 UST ID: 8917 Site Page Site Documents View Map

Cleanup Site Name: Whidbey Marine & Auto Supply

Alternate Names: Whidbey Marine, Whidbey Marine & Auto, WHIDBEY MARINE & AUTO SUPPLY

LOCATION

Address: 1695 MAIN ST City: FREELAND Zip Code: 98249 County: Island

Latitude: 48.00993 Longitude: -122.52366 WRIA: 6 Legislative District: 10 Congressional District: 2 TRS: 29N 2E 11

DETAIL

Status: Cleanup Started NFA Received? No Is PSI site? Yes

Statute: MTCA NFA Date: N/A Current VCP? No Past VCP? Yes

Site Rank: N/A NFA Reason: N/A Brownfield? No

Site Manager: Rapp, John Responsible Unit: Northwest Active Institutional Control? No

**CLEANUP UNITS** 

 
 Cleanup Unit Name
 Unit Type
 Unit Status
 Resp Unit
 Unit Manager
 Current Process

 Whidbey Marine & Auto Supply
 Upland
 Cleanup Started
 NW
 Rapp, John
 Ecology-supervised or conducted

**ACTIVE INSTITUTIONAL CONTROLS** 

Instrument Type Restriction Media Restrictions/Requirements Date Recording Number County Tax Parcel

There are no current Institutional Controls in effect for this site.

## AFFECTED MEDIA & CONTAMINANTS

	MEDIA					
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Benzene	С	С				
Other Non-Halogenated Organics	С	С				
Petroleum-Diesel	С	С				
Petroleum-Gasoline	С	С				

Key:

B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above S - Suspected R - Remediated RB - Remediated-Below

## SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
SHARP Assessment	Completed		
LUST - Notification	Completed		9/28/2005
Site Discovery/Release Report Received	Completed		9/28/2005
VCP Opinion on Interim Action	Completed	12/7/2005	2/1/2006
VCP Opinion on Interim Action	Completed	3/13/2007	3/19/2007
VCP Opinion on Interim Action	Canceled	7/6/2007	1/1/1900
VCP Opinion on Interim Action	Completed	9/17/2007	9/20/2007

Toxics Cleanup Program Report Generated: 6/6/2025 Page 1 of 2



## Cleanup Site Details

Cleanup Site ID: 5610

SITE ACTIVITIES						
vity Status		Start Date	End Date/ Completion Date			
VCP Status Request	Completed	1/13/2010	2/13/2010			
VCP Opinion on Remedial Investigation	Completed	1/15/2010	1/26/2010			
LUST - Report Received	Completed		5/5/2011			
VCP Opinion on Site Cleanup	Completed	3/7/2013	6/3/2013			
VCP Receipt of Plan or Report	Completed		7/11/2014			
VCP Receipt of Plan or Report	Completed		1/14/2015			
VCP Receipt of Plan or Report	Completed		5/26/2015			
VCP Receipt of Plan or Report	Completed		10/9/2015			
VCP Receipt of Plan or Report	Completed		1/8/2016			
VCP Receipt of Plan or Report	Completed		4/19/2016			