

# Cleanup Site Details

Cleanup Site ID: 5686

Cleanup Site ID: 5686      Facility/Site ID: 21515785      UST ID: 513232      [Site Page](#)      [Site Documents](#)      [View Map](#)

Cleanup Site Name: Totem Pole Restaurant      [Glossary](#)

Alternate Names: TOTEM POLE RESTAURANT

## LOCATION

Address: 7720 NE HWY 99      City: VANCOUVER      Zip Code: 98665      County: Clark  
Latitude: 45.67915      Longitude: -122.66163      WRIA: 28      Legislative District: 49      Congressional District: 3      TRS: 2N 1E 37

## DETAIL

Status: No Further Action      NFA Received? Yes      Is PSI site? No  
Statute: MTCA      NFA Date: 6/30/2006      Current VCP? No      Past VCP? Yes  
Site Rank: N/A      NFA Reason: Voluntary Cleanup Program Review      Brownfield? No  
Site Manager: Rose, Scott      Responsible Unit: Southwest      Active Institutional Control? Yes

## CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
TOTEM POLE RESTAURANT	Upland	No Further Action Required	SW	Southwest Region	Standard Voluntary Cleanup

## ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
Environmental Covenant	Soil, Groundwater	Restrict Land Use, Restrict All Ground Water Extraction/Well Installation, Prohibit Soil Disturbance	10/10/2000	3259370	Clark	147997000, 148041000

Institutional Control documents may be available under the 'Site Documents' link at the top of the page. For more details on Institutional Controls, please see the [Environmental Covenants Registry List](#).

## AFFECTED MEDIA & CONTAMINANTS

MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Petroleum-Other	C	C				

**Key:**  
B - Below Cleanup Level      C - Confirmed Above Cleanup Level      RA - Remediated-Above  
S - Suspected      R - Remediated      RB - Remediated-Below

## SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
LUST - Notification	Completed		4/30/1999
LUST - Site Characterization Report	Completed		6/25/1999
Independent Report Review - Unpaid	Completed	7/6/1999	6/30/2006
VCP Opinion on Cleanup Action	Completed	7/6/1999	12/21/2000
LUST - Site Characterization Report	Completed		10/14/1999
LUST - Report Received	Completed		8/11/2000
LUST - Report Received	Completed		8/11/2000
LUST - Report Received	Completed		9/7/2000
LUST - Report Received	Completed		9/7/2000

# Cleanup Site Details

Cleanup Site ID: 5686

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
LUST - Report Received	Completed		12/26/2000
Reopen Site	Completed		8/5/2004
VCP Opinion on Cleanup Action Plan	Completed	5/20/2006	6/30/2006
Site Status Changed to NFA	Completed		6/30/2006
Periodic Review	Completed	12/20/2011	2/3/2012
Periodic Review	Completed	8/1/2016	11/13/2016
Periodic Review	Completed	8/1/2021	10/23/2022
Periodic Review	Planned	8/23/2027	1/1/1900