

# Cleanup Site Details

Cleanup Site ID: 5798

**Cleanup Site ID:** 5798      **Facility/Site ID:** 27223439      **UST ID:** 564219      [Site Page](#)      [Site Documents](#)      [View Map](#)  
**Cleanup Site Name:** Chevron Station 98944      [Glossary](#)  
**Alternate Names:** CHEVRON 98944, CHEVRON STATION 98944

## LOCATION

**Address:** 1323 LEE BLVD      **City:** RICHLAND      **Zip Code:** 99352      **County:** Benton  
**Latitude:** 46.27468      **Longitude:** -119.28151      **WRIA:** 40      **Legislative District:** 8      **Congressional District:** 4      **TRS:** 9N 28E 11

## DETAIL

**Status:** Cleanup Started      **NFA Received?** No      **Is PSI site?** No  
**Statute:** MTCA      **NFA Date:** N/A      **Current VCP?** No      **Past VCP?** Yes  
**Site Rank:** 3 - Moderate Risk      **NFA Reason:** N/A      **Brownfield?** No  
**Site Manager:** Caron, Rachel      **Responsible Unit:** Central      **Active Institutional Control?** No

## CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Chevron 98944	Upland	Cleanup Started	CE	Caron, Rachel	Ecology-supervised or conducted

## ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

## AFFECTED MEDIA & CONTAMINANTS

### MEDIA

Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Benzene	B	C				
Methyl tertiary-butyl ether		B				
Petroleum-Gasoline	B	C				

### Key:

B - Below Cleanup Level      C - Confirmed Above Cleanup Level      RA - Remediated-Above  
S - Suspected      R - Remediated      RB - Remediated-Below

## SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
LUST - Notification	Completed		10/25/1994
LUST - Site Characterization Report	Completed		10/25/1994
Site Discovery/Release Report Received	Completed		10/27/1994
LUST - Report Received	Completed		4/17/2000
Initial Investigation / Federal Preliminary Assessment	Completed		4/20/2000
Early Notice Letter(s)	Completed		4/24/2000
LUST - Report Received	Completed		4/23/2001
LUST - Report Received	Completed		1/22/2002

# Cleanup Site Details

Cleanup Site ID: 5798

<b>SITE ACTIVITIES</b>			
<b>Activity</b>	<b>Status</b>	<b>Start Date</b>	<b>End Date/ Completion Date</b>
LUST - Report Received	Completed		11/4/2002
LUST - Report Received	Completed		10/17/2003
LUST - Report Received	Completed		4/19/2004
LUST - Report Received	Completed		10/4/2004
LUST - Report Received	Completed		1/27/2005
VCP Opinion on Interim Action	Completed	1/30/2006	4/25/2006
LUST - Report Received	Completed		4/3/2006
LUST - Report Received	Completed		4/3/2006
LUST - Report Received	Completed		4/17/2006
LUST - Report Received	Completed		6/19/2007
LUST - Report Received	Completed		12/12/2007
LUST - Report Received	Completed		1/5/2008
LUST - Report Received	Completed		3/5/2008
LUST - Report Received	Completed		9/26/2008
LUST - Report Received	Completed		3/25/2009
LUST - Report Received	Completed		4/23/2009
LUST - Report Received	Completed		11/22/2010
LUST - Report Received	Completed		11/21/2011
Site Hazard Assessment/Federal Site Inspection	Completed	6/30/2014	12/17/2014
Hazardous Sites Listing/NPL	Completed		1/6/2015
Order/Decree/Amendment	In Process	11/21/2017	
Remedial Investigation and/or FS Work Plan	Completed	7/15/2018	7/24/2018
LUST - Report Received	Completed		7/23/2018
Cleanup - Performance Monitoring	In Process	7/24/2018	
LUST - Report Received	Completed		1/16/2019
Remedial Investigation and/or Feasibility Study	In Process	1/13/2020	
LUST - Report Received	Completed		2/6/2020
LUST - Report Received	Completed		7/11/2022