

Cleanup Site Details

Cleanup Site ID: 5798

Cleanup Site ID: 5798 Facility/Site ID: 27223439 UST ID: 564219 [Site Page](#) [Site Documents](#) [View Map](#)

Cleanup Site Name: Chevron Station 98944 [Glossary](#)

Alternate Names: CHEVRON 98944, CHEVRON STATION 98944

LOCATION

Address: 1323 LEE BLVD City: RICHLAND Zip Code: 99352 County: Benton
Latitude: 46.27468 Longitude: -119.28151 WRIA: 40 Legislative District: 8 Congressional District: 4 TRS: 9N 28E 11

DETAIL

Status: Cleanup Started NFA Received? No Is PSI site? No
Statute: MTCA NFA Date: N/A Current VCP? No Past VCP? Yes
Site Rank: 3 - Moderate Risk NFA Reason: N/A Brownfield? No
Site Manager: Caron, Rachel Responsible Unit: Central Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Chevron 98944	Upland	Cleanup Started	CE	Caron, Rachel	Ecology-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

MEDIA

Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Benzene	B	C				
Methyl tertiary-butyl ether		B				
Petroleum-Gasoline	B	C				

Key:
B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
LUST - Notification	Completed		10/25/1994
LUST - Site Characterization Report	Completed		10/25/1994
Site Discovery/Release Report Received	Completed		10/27/1994
LUST - Report Received	Completed		4/17/2000
Initial Investigation / Federal Preliminary Assessment	Completed		4/20/2000
Early Notice Letter(s)	Completed		4/24/2000
LUST - Report Received	Completed		4/23/2001
LUST - Report Received	Completed		1/22/2002

Cleanup Site Details

Cleanup Site ID: 5798

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
LUST - Report Received	Completed		11/4/2002
LUST - Report Received	Completed		10/17/2003
LUST - Report Received	Completed		4/19/2004
LUST - Report Received	Completed		10/4/2004
LUST - Report Received	Completed		1/27/2005
VCP Opinion on Interim Action	Completed	1/30/2006	4/25/2006
LUST - Report Received	Completed		4/3/2006
LUST - Report Received	Completed		4/3/2006
LUST - Report Received	Completed		4/17/2006
LUST - Report Received	Completed		6/19/2007
LUST - Report Received	Completed		12/12/2007
LUST - Report Received	Completed		1/5/2008
LUST - Report Received	Completed		3/5/2008
LUST - Report Received	Completed		9/26/2008
LUST - Report Received	Completed		3/25/2009
LUST - Report Received	Completed		4/23/2009
LUST - Report Received	Completed		11/22/2010
LUST - Report Received	Completed		11/21/2011
Site Hazard Assessment/Federal Site Inspection	Completed	6/30/2014	12/17/2014
Hazardous Sites Listing/NPL	Completed		1/6/2015
Order/Decree/Amendment	In Process	11/21/2017	
Remedial Investigation and/or FS Work Plan	Completed	7/15/2018	7/24/2018
LUST - Report Received	Completed		7/23/2018
Cleanup - Performance Monitoring	In Process	7/24/2018	
LUST - Report Received	Completed		1/16/2019
Remedial Investigation and/or Feasibility Study	In Process	1/13/2020	
LUST - Report Received	Completed		2/6/2020
LUST - Report Received	Completed		7/11/2022