

Cleanup Site Details

Cleanup Site ID: 58

Cleanup Site ID: 58 Facility/Site ID: 2105 UST ID: N/A [Site Page](#) [Site Documents](#) [View Map](#)

Cleanup Site Name: BSB Diversified Co Inc [Glossary](#)

Alternate Names: BSB DIVERSIFIED, BSB DIVERSIFIED & HEXCEL CORP, BSB Diversified Co Inc, Heath Plating, HYTEK FINISHES CO 200TH ST, HYTEK FINISHING CO

LOCATION

Address: 8202 S 200TH ST City: KENT Zip Code: 98032 County: King
Latitude: 47.42280 Longitude: -122.23045 WRIA: 9 Legislative District: 33 Congressional District: 9 TRS: 22N 4E 1

DETAIL

Status: Cleanup Started NFA Received? No Is PSI site? No
Statute: MTCA (RCRA Corrective Action) NFA Date: N/A Current VCP? No Past VCP? No
Site Rank: 1 - Highest Assessed Risk NFA Reason: N/A Brownfield? No
Site Manager: Hobbs, Erin Responsible Unit: Hazardous Waste Active Institutional Control? Yes

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
BSB Diversified Co Inc	Upland	Cleanup Started	HWTR	Hobbs, Erin	Ecology-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
Environmental Covenant	Groundwater, Soil	Restrict All Ground Water Extraction/Well Installation, Restrict Domestic Ground Water Extraction/Well Installation, Prohibit Soil Disturbance	4/5/2012	20120405000599	King	0122049117

Institutional Control documents may be available under the 'Site Documents' link at the top of the page. For more details on Institutional Controls, please see the [Environmental Covenants Registry List](#).

AFFECTED MEDIA & CONTAMINANTS

Contaminant	MEDIA					
	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Base/Neutral/Acid Organics		S				
Corrosive Wastes	S	S				
Halogenated Organics	C	C				
Metals - Other	S	C				
Metals Priority Pollutants	S	C				
Non-Halogenated Solvents		S				
Phenolic Compounds		S				

Key:
B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/Completion Date
Site Discovery/Release Report Received	Completed		3/1/1988
Site Hazard Assessment/Federal Site Inspection	Completed		4/1/2004

Cleanup Site Details

Cleanup Site ID: 58

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
Hazardous Sites Listing/NPL	Completed		10/20/2009
Periodic Review	In Process	8/21/2018	