

Cleanup Site Details

Cleanup Site ID: 58

Cleanup Site ID: 58 Facility/Site ID: 2105 UST ID: N/A [Site Page](#) [Site Documents](#) [View Map](#)

Cleanup Site Name: BSB Diversified Co Inc [Glossary](#)

Alternate Names: BSB DIVERSIFIED, BSB DIVERSIFIED & HEXCEL CORP, BSB Diversified Co Inc, Heath Plating, HYTEK FINISHES CO 200TH ST, HYTEK FINISHING CO

LOCATION

Address: 8202 S 200TH ST **City:** KENT **Zip Code:** 98032 **County:** King
Latitude: 47.42280 **Longitude:** -122.23045 **WRIA:** 9 **Legislative District:** 33 **Congressional District:** 9 **TRS:** 22N 4E 1

DETAIL

Status: Cleanup Started **NFA Received?** No **Is PSI site?** No
Statute: MTCA (RCRA Corrective Action) **NFA Date:** N/A **Current VCP?** No **Past VCP?** No
Site Rank: 1 - Highest Assessed Risk **NFA Reason:** N/A **Brownfield?** No
Site Manager: Hobbs, Erin **Responsible Unit:** Hazardous Waste **Active Institutional Control?** Yes

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
BSB Diversified Co Inc	Upland	Cleanup Started	HWTR	Hobbs, Erin	Ecology-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
Environmental Covenant	Groundwater, Soil	Restrict All Ground Water Extraction/Well Installation, Restrict Domestic Ground Water Extraction/Well Installation, Prohibit Soil Disturbance	4/5/2012	20120405000599	King	0122049117

Institutional Control documents may be available under the 'Site Documents' link at the top of the page. For more details on Institutional Controls, please see the [Environmental Covenants Registry List](#).

AFFECTED MEDIA & CONTAMINANTS

Contaminant	MEDIA					
	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Base/Neutral/Acid Organics		S				
Corrosive Wastes	S	S				
Halogenated Organics	C	C				
Metals - Other	S	C				
Metals Priority Pollutants	S	C				
Non-Halogenated Solvents		S				
Phenolic Compounds		S				

Key:
B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/Completion Date
Site Discovery/Release Report Received	Completed		3/1/1988
Site Hazard Assessment/Federal Site Inspection	Completed		4/1/2004

Cleanup Site Details

Cleanup Site ID: 58

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
Hazardous Sites Listing/NPL	Completed		10/20/2009
Periodic Review	In Process	8/21/2018	