

Cleanup Site Details

Cleanup Site ID: 5818

Cleanup Site ID: 5818 Facility/Site ID: 28575673 UST ID: 3749 [Site Page](#) [Site Documents](#) [View Map](#)

Cleanup Site Name: Gold Nugget Market [Glossary](#)

Alternate Names: Gold Nugget Market, GOLD NUGGET MINIMART

LOCATION

Address: 1041 BUENA RD City: BUENA Zip Code: 98921 County: Yakima

Latitude: 46.42699 Longitude: -120.31333 WRIA: 37 Legislative District: 15 Congressional District: 4 TRS:

DETAIL

Status: Cleanup Started	NFA Received? No	Is PSI site? No
Statute: MTCA	NFA Date: N/A	Current VCP? No Past VCP? No
Site Rank: 5 - Lowest Assessed Risk	NFA Reason: N/A	Brownfield? No
Site Manager: Wisotzkey, Chelsea	Responsible Unit: Central	Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Gold Nugget Market	Upland	Cleanup Started	CE	Wisotzkey, Chelsea	Ecology-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

MEDIA

Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Petroleum-Gasoline	C	C				

Key:
 B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
 S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
LUST - Site Characterization Report	Completed		1/1/1900
Initial Investigation / Federal Preliminary Assessment	Completed		10/4/1985
Early Notice Letter(s)	Completed		7/28/1992
Hazardous Sites Listing	Completed		9/7/1993
LUST - Notification	Completed		10/8/1998
Initial Investigation / Federal Preliminary Assessment	Completed		8/16/1999
Early Notice Letter(s)	Completed		2/28/2000
LUST - Report Received	Completed		2/28/2000
LUST - Report Received	Completed		1/9/2001
Site Hazard Assessment	Completed	2/28/2001	12/26/2002

Cleanup Site Details

Cleanup Site ID: 5818

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
Interim Action - Plan	Completed	1/1/2013	3/9/2013
Interim Action - Construction	Completed	8/20/2013	9/15/2014
Interim Action - Performance Monitoring	Completed	10/31/2014	7/1/2015
SHARP Assessment	Completed		4/30/2024
LUST Review Memo	Completed		5/6/2024