

Cleanup Site Details

Cleanup Site ID: 5818

Cleanup Site ID: 5818 **Facility/Site ID:** 28575673 **UST ID:** 3749 [Site Page](#) [Site Documents](#) [View Map](#)
Cleanup Site Name: Gold Nugget Market [Glossary](#)
Alternate Names: Gold Nugget Market, GOLD NUGGET MINIMART

LOCATION

Address: 1041 BUENA RD **City:** BUENA **Zip Code:** 98921 **County:** Yakima
Latitude: 46.42699 **Longitude:** -120.31333 **WRIA:** 37 **Legislative District:** 15 **Congressional District:** 4 **TRS:**

DETAIL

Status: Cleanup Started **NFA Received?** No **Is PSI site?** No
Statute: MTCA **NFA Date:** N/A **Current VCP?** No **Past VCP?** No
Site Rank: 5 - Lowest Assessed Risk **NFA Reason:** N/A **Brownfield?** No
Site Manager: Wisotzkey, Chelsea **Responsible Unit:** Central **Active Institutional Control?** No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Gold Nugget Market	Upland	Cleanup Started	CE	Wisotzkey, Chelsea	Ecology-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Petroleum-Gasoline	C	C				

Key:
B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
LUST - Site Characterization Report	Completed		
Initial Investigation / Federal Preliminary Assessment	Completed		10/4/1985
Early Notice Letter(s)	Completed		7/28/1992
Hazardous Sites Listing/NPL	Completed		9/7/1993
LUST - Notification	Completed		10/8/1998
Initial Investigation / Federal Preliminary Assessment	Completed		8/16/1999
Early Notice Letter(s)	Completed		2/28/2000
LUST - Report Received	Completed		2/28/2000
LUST - Report Received	Completed		1/9/2001
Site Hazard Assessment/Federal Site Inspection	Completed	2/28/2001	12/26/2002

Cleanup Site Details

Cleanup Site ID: 5818

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
Interim Action - Plan	Completed	1/1/2013	3/9/2013
Interim Action - Construction	Completed	8/20/2013	9/15/2014
Interim Action - Performance Monitoring	Completed	10/31/2014	7/1/2015