

Cleanup Site Details

Cleanup Site ID: 5846

Cleanup Site ID: 5846 Facility/Site ID: 31164291 UST ID: 4656 [Site Page](#) [Site Documents](#) [View Map](#)

Cleanup Site Name: Montesano Farm & Home [Glossary](#)

Alternate Names: GRAYS HARBOR GRANGE SUPPLY, GRAYS HARBOR GRANGE SUPPLY UST 4656, MASCO PETROLEUM MONTESANO, MONTESANO FARM & HOME, MONTESANO FARM AND HOME

LOCATION

Address: 412 MAIN ST S **City:** MONTESANO **Zip Code:** 98563 **County:** Grays Harbor
Latitude: 46.97827 **Longitude:** -123.60066 **WRIA:** 22 **Legislative District:** 19 **Congressional District:** 6 **TRS:** 17N 7W 7

DETAIL

Status: No Further Action **NFA Received?** Yes **Is PSI site?** No
Statute: MTCA **NFA Date:** 4/21/2010 **Current VCP?** No **Past VCP?** Yes
Site Rank: N/A **NFA Reason:** Voluntary Cleanup Program Review **Brownfield?** No
Site Manager: Middleton, Tom **Responsible Unit:** Southwest **Active Institutional Control?** Yes

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
MONTESANO FARM AND HOME	Upland	No Further Action Required	SW	Southwest Region	Standard Voluntary Cleanup

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
Environmental Covenant	Soil	Prohibit Soil Disturbance	5/6/2006	200605080120	Grays Harbor	075300100100

Institutional Control documents may be available under the 'Site Documents' link at the top of the page. For more details on Institutional Controls, please see the [Environmental Covenants Registry List](#).

AFFECTED MEDIA & CONTAMINANTS

MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Petroleum-Other	C	C				

Key:
 B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
 S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
LUST - Notification	Completed		9/13/1991
LUST - Report Received	Completed		9/23/1991
Site Characterization	Completed	7/1/1997	2/28/2004
LUST - Site Characterization Report	Completed		6/2/1999
LUST - Report Received	Completed		12/25/2003
LUST - Site Characterization Report	Completed		2/23/2004
LUST - Report Received	Completed		5/11/2004
VCP Opinion on Remedial Investigation Work Plan	Completed	5/21/2004	3/27/2006
Routine Cleanup	Completed	6/10/2004	12/31/2005

Cleanup Site Details

Cleanup Site ID: 5846

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
Site Discovery/Release Report Received	Completed		11/15/2005
Remedial Investigation and/or Feasibility Study	Completed	3/30/2007	3/30/2009
VCP Opinion on Cleanup Action	Completed	3/14/2010	4/21/2010
Site Status Changed to NFA	Completed		4/21/2010
Periodic Review	Completed	12/10/2011	2/27/2012
Periodic Review	Completed	9/1/2016	12/12/2016
Periodic Review	Completed	9/1/2021	9/11/2022
Periodic Review	Planned	7/11/2027	1/1/1900