

Cleanup Site ID: 589

Cleanup Site Details

UST ID: N/A

Cleanup Site ID: 589

Site Page

Site Documents

View Map

Cleanup Site Name: Mason County Salvage Yard **Glossary**

Alternate Names: MASON CNTY SALVAGE YARD, Mason County Salvage, Mason County Salvage Yard

Facility/Site ID: 7638537

LOCATION

Address: 1840 W CLOQUALLUM RD City: SHELTON **Zip Code:** 98584 County: Mason

Latitude: 47.16970 Longitude: -123.12773 **WRIA**: 14 Legislative District: 35 Congressional District: 6 **TRS**: 19N 4W 1

DETAIL

NFA Received? Is PSI site? Status: No No **Awaiting Cleanup**

MTCA NFA Date: **Current VCP?** Past VCP? No Statute: N/A No

Site Rank: 3 - Moderate Risk NFA Reason: N/A Brownfield?

Site Manager: Southwest Region Responsible Unit: Southwest **Active Institutional Control?** No

CLEANUP UNITS

Resp **Cleanup Unit Name Unit Type Unit Status Unit Manager Current Process** Unit MASON CNTY SALVAGE YARD SW No Process Upland **Awaiting Cleanup** Southwest Region

ACTIVE INSTITUTIONAL CONTROLS

Restriction Recording Recording **Tax Parcel Instrument Type** Restrictions/Requirements Date Media Number County

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

		MEDIA					
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock	
Metals Priority Pollutants	S						
Petroleum Products-Unspecified	С						
Polycyclic Aromatic Hydrocarbons	В						

Key:

B - Below Cleanup Level C - Confirmed Above Cleanup Level S - Suspected

RA - Remediated-Above R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Initial Investigation / Federal Preliminary Assessment	Completed		3/25/2003
Site Discovery/Release Report Received	Completed		3/25/2003
Early Notice Letter(s)	Completed		7/7/2003
Site Hazard Assessment/Federal Site Inspection	Completed	4/25/2007	2/26/2008
Hazardous Sites Listing/NPL	Completed		2/26/2008

Toxics Cleanup Program Report Generated: 6/18/2025 Page 1 of 1