

# Cleanup Site Details

Cleanup Site ID: 5917

Cleanup Site ID: 5917      Facility/Site ID: 34717571      UST ID: 100902      [Site Page](#)      [Site Documents](#)      [View Map](#)

Cleanup Site Name: Benton City Maintenance Yard      [Glossary](#)

Alternate Names: BENTON CITY MAINTENANCE YARD

## LOCATION

Address: 509 7TH ST      City: BENTON CITY      Zip Code: 99320      County: Benton  
Latitude: 46.26324      Longitude: -119.48454      WRIA: 37      Legislative District: 16      Congressional District: 4      TRS: 9N 27E 18

## DETAIL

Status: No Further Action      NFA Received? Yes      Is PSI site? No  
Statute: MTCA      NFA Date: 8/20/2007      Current VCP? No      Past VCP? No  
Site Rank: 3 - Moderate Risk      NFA Reason: Independent Cleanup Reviewed by Ecology      Brownfield? No  
Site Manager: Deeken, Brian      Responsible Unit: Central      Active Institutional Control? No

## CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Benton City Shop	Upland	No Further Action Required	CE	Central Region	Independent Action

## ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

## AFFECTED MEDIA & CONTAMINANTS

MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Petroleum Products-Unspecified		S				
Petroleum-Diesel	RB					
Petroleum-Gasoline	RB					

### Key:

B - Below Cleanup Level      C - Confirmed Above Cleanup Level      RA - Remediated-Above  
S - Suspected      R - Remediated      RB - Remediated-Below

## SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Site Discovery/Release Report Received	Completed		8/9/1991
LUST - Notification	Completed		8/9/1991
LUST - Site Characterization Report	Completed		1/27/1992
Site Hazard Assessment	Completed	11/8/2006	1/24/2007
Hazardous Sites Listing	Completed		1/24/2007
LUST - Report Received	Completed		3/9/2007
LUST - Site Assessment Report	Completed		3/9/2007

# Cleanup Site Details

**Cleanup Site ID: 5917**

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
Remove site from Hazardous Sites List	Completed		8/20/2007
Site Status Changed to NFA	Completed		8/20/2007