

Cleanup Site Details

Cleanup Site ID: 5935

Cleanup Site ID: 5935 Facility/Site ID: 35723331 UST ID: 1425 [Site Page](#) [Site Documents](#) [View Map](#)

Cleanup Site Name: Haskell Corporation [Glossary](#)

Alternate Names: HASKELL BUSINESS CENTER, HASKELL CORP, HASKELL CORP (FORMER), HASKELL CORP BELLINGHAM, Haskell Corporation

LOCATION

Address: 1001 MEADOR AVE **City:** BELLINGHAM **Zip Code:** 98229 **County:** Whatcom
Latitude: 48.75336 **Longitude:** -122.46115 **WRIA:** 1 **Legislative District:** 40 **Congressional District:** 2 **TRS:**

DETAIL

Status: No Further Action **NFA Received?** Yes **Is PSI site?** No
Statute: MTCA **NFA Date:** 11/2/2001 **Current VCP?** No **Past VCP?** Yes
Site Rank: N/A **NFA Reason:** Voluntary Cleanup Program Review **Brownfield?** No
Site Manager: O'Herron, Mary **Responsible Unit:** Northwest **Active Institutional Control?** Yes

CLEANUP UNITS

| Cleanup Unit Name | Unit Type | Unit Status | Resp Unit | Unit Manager | Current Process |
|---------------------|-----------|----------------------------|-----------|----------------|----------------------------|
| Haskell Corporation | Upland | No Further Action Required | NW | O'Herron, Mary | Standard Voluntary Cleanup |

ACTIVE INSTITUTIONAL CONTROLS

| Instrument Type | Restriction Media | Restrictions/Requirements | Date | Recording Number | Recording County | Tax Parcel |
|------------------------|-------------------|-------------------------------|-----------|------------------|------------------|--|
| Environmental Covenant | Soil | Ongoing Maintenance of Remedy | 9/13/2001 | 2010901524 | Whatcom | 380329124333; 380329139337; 380329149337 |

Institutional Control documents may be available under the 'Site Documents' link at the top of the page. For more details on Institutional Controls, please see the [Environmental Covenants Registry List](#).

AFFECTED MEDIA & CONTAMINANTS

| MEDIA | | | | | | |
|-----------------|------|-------------|---------------|----------|-----|---------|
| Contaminant | Soil | Groundwater | Surface Water | Sediment | Air | Bedrock |
| Petroleum-Other | C | | | | | |

Key:
B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

| Activity | Status | Start Date | End Date/ Completion Date |
|-------------------------------|-----------|------------|------------------------------|
| LUST - Notification | Completed | | 2/4/1991 |
| LUST - Report Received | Completed | | 6/12/1991 |
| LUST - Report Received | Completed | | 8/28/1991 |
| LUST - Report Received | Completed | | 8/10/1992 |
| Cleanup Action Plan | Completed | 10/17/2000 | 1/17/2001 |
| VCP Opinion on Interim Action | Completed | 10/17/2000 | 10/30/2001 |
| Site Status Changed to NFA | Completed | | 11/2/2001 |
| Periodic Review | Completed | 5/31/2011 | 9/26/2011 |

Cleanup Site Details

Cleanup Site ID: 5935

| SITE ACTIVITIES | | | |
|-----------------|-----------|------------|------------------------------|
| Activity | Status | Start Date | End Date/ Completion Date |
| Periodic Review | Completed | 9/15/2016 | 11/1/2016 |
| Periodic Review | Planned | 9/1/2021 | 1/1/1900 |