

# Cleanup Site Details

Cleanup Site ID: 599 Facility/Site ID: 23881883 UST ID: N/A Site Page Site Documents View Map

Cleanup Site ID: 599

Cleanup Site Name: Glacier Northwest Inc

Alternate Names: 5900 W MARGINAL WAY SW, Glacier Northwest Inc, GLACIER NORTHWEST INC SEA, Glacier NW, REICHOLD CHEMICAL

LONE STAR

LOCATION

Address: 5900 W MARGINAL WAY SW City: SEATTLE Zip Code: 98106 County: King

Latitude: 47.54938 Longitude: -122.34438 WRIA: 9 Legislative District: 34 Congressional District: 7 TRS: 24N 4E 19

**DETAIL** 

Status: Cleanup Started NFA Received? No Is PSI site? No

Statute: MTCA NFA Date: N/A Current VCP? No Past VCP? No

Site Rank: 1 - Highest Assessed Risk NFA Reason: N/A Brownfield? No

Site Manager: Nale, Cliff Responsible Unit: Northwest Active Institutional Control? No

**CLEANUP UNITS** 

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Glacier Northwest Inc	Upland	Cleanup Started	NW	Nale, Cliff	Ecology-supervised or conducted

### **ACTIVE INSTITUTIONAL CONTROLS**

There are no current Institutional Controls in effect for this site.

## **AFFECTED MEDIA & CONTAMINANTS**

MEDIA						
Soil	Groundwater	Surface Water	Sediment	Air	Bedrock	
С	С	С				
С						
	В					
С	С	В				
	В					
С						
С	С	С				
С	S					
	В					
	C C C C	C C C C B C C C C C S	Soil Groundwater Surface Water   C C C   C B B   C C B   B C C   C C C   C C C   C C C   C C C	Soil Groundwater Surface Water Sediment   C C C   C B B   C C B   B C C   C C C   C C C   C C C   C C C	Soil Groundwater Surface Water Sediment Air   C	

Key

B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above S - Suspected R - Remediated RB - Remediated-Below

### SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Site Discovery/Release Report Received	Completed		3/1/1988

Toxics Cleanup Program Report Generated: 11/12/2025 Page 1 of 2



# Cleanup Site Details

SITE ACTIVITIES					
Activity	Status	Start Date	End Date/ Completion Date		
Hazardous Sites Listing	Completed		8/27/1991		
Site Hazard Assessment	Completed		8/27/1991		
Order/Decree/Amendment	In Process	10/1/2008			
Remedial Investigation and/or FS Work Plan	Completed	8/1/2010	9/26/2013		
Remedial Investigation and/or Feasibility Study	In Process	9/26/2013			
Remedial Investigation and/or Feasibility Study	In Process	6/1/2018			
SHARP Assessment	Completed		9/2/2025		

Cleanup Site ID: 599